Certificate of Location of Government Corner

ID#: 742509 **Description:** SEC CEN 25 74 **Date Set:** 1/23/2004 **County:** Olmsted

Section: 25 **Township:** 107N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' south of E-W chain link fence and 84' west of centerline 19th St NE on curve
NW corner house #826 SSW 29.51'
SE corner house #820 walkway N 39.59'
This corner is located by GPS reference stations "Yawn A & B"

Corner History:

5-1856 T. Hunter Pg. 8 No. 13 Shows cetner sec., 1/16 west 20.71 chs. M&L to 1/4 post. 1/16 South 19.73 chs. M&L to 1/4 post. Center of SW 1/4 meas. west 20.28 & 19.66 chs. North to describe NW 1/4 of SW 1/4 sec. 25.

9-1858 T. Hunter Pg. 56 No. 82 Shows center sec. meas. west 41.42 chs. to 1/4 post, 1/16 East 19.67 chs. M&L to 1/4 post, 1/16 North 19.97 chs. (See survey for breakdown in N1/2 Sec. 25.

7-1859 T. Hunter Pg. 62, No.88 shows cen. sec. 1/16 south 19.73 chs. M&L to 1/4 post.

1863 P.C. Compton Bk.A; Set center 25 at intersecting 1/4 lines. Big tree given, but should check at courthouse.

8-30-1961 J.Kerr found limestone and set CIM in its place.

4-6-1990 County Surveyor found CIM with top broken off but bottom seems good, left as is.

1-20-2004 County Surveyor found CIM with head broken off along fence down 0.6' in good condition.

1-23-2004 County Surveyor found CIM with head broken off down 0.6', took local ties and removed. Set 5' telspar with CIC from ties at surface. Did not check ties because of weather.

8-15-2007 County Surveyor found CIC on telspar pipe at surface in good condition.