Certificate of Location of Government Corner

ID#: 742805 **Description:** SEC COR 28 29 32 33 74 **Date Set:** 8/14/2007 **County:** Olmsted

Section: 28 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 44 1/2' SW of centerline of TH 14 exit ramp at CSAH 22 interchange
Post w/sign 2' SW
This corner is located by GPS reference stations "Exit & Entrance"

Corner History:

1854 Gov't Notes, Karrick, Deputy Surveyor, North between sections 32 and 33. 80.00 chs. Set post in mound with trench pits, charred stake, and osage orange seeds at each angle.

10-1894 William Fraser (P. 554 No. 511), County Surveyor, found corner post of fences given by Hunter as corner.

T. Hunter's tie to railroad-983' north to centerline of tracks.

3-1954 John Kerr (B. 57 P. 64), County Surveyor, measured 983' south from center line of railroad track. Dug and found old post remains. Set 1" pipe in hole.

11-19-1971 County Surveyor found 1" pipe found by McGhie and Betts in previous survey. Set C.I.M. over 1" pipe driven down.

1-16-1974 County Surveyor reset C.I.M. after previous one broken. Found Kerr's pipe beneath monument.

7-1996 County Surveyor found CIM in good condition. Set sign and post ± 1.0' southerly.

2-12-2002 County Surveyor visited area and found corner is gone due to construction of CSAH 22 and TH 14 interchange.

8-14-2007 County Surveyor set 5' telspar pipe w/cast iron cap down 0.1' from GPS and traverse data. Set post w/sign.