Certificate of Location of Government Corner

ID#: 742904 **Description:** 1/4 SEC COR 29 32 74 **Date Set:** **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 14W **Monument Description:**

Reference Ties:

This corner is located by GPS reference stations "Pink Door A & B"

Corner History:

6-1854 Gov't Notes, M Karrick, Deputy Surveyor, West of true line between sections 29 and 32. 40.00 chs. Set quarter section post. Jack Oak 7" N20ºW 220 lks. Dug trench. 80.00 chs. To section corner.

11-1856 Thomas Hunter, Co. Surveyor, (Book A Page 19 No. 31) possibly used this corner to set the Center 32 which he used in a survey in the SW1/4 Sec. 32.

4-1858 T. Hunter (Book A Page 52 No. 75) possibly used this corner to set the Center 29 which he used for a survey in the N1/2 Sec. 29.

10-1894 William Fraser, Deputy County Surveyor, (Book A Page 555 No. 572) found a stake marked 1/4 corner in the center of a mound. Planted a stone in its place. Set a temporary stake at the Center 32 at intersecting 1/4 lines after setting the S. 1/4 Cor. 32 midway and on line between the section corners.

1957 Ken McGhie used "the fence line in place 600' ± north of the North line of S1/2 of NE1/4 (Sec. 32) extended West "as E-W control to set an 11/4" pipe as the Center 32 at intersecting 1/4 lines. He used a point midway and on line as the S. 1/4 Cor. 32.

10-1963 John Kerr found the rod set by McGhie at the S. 1/4 Cor. 32 and set a C.I.M. at this point.

1971 County Surveyor searched for this corner after measureing Will Fraser's distance west from Section Corner 28-29-32-33 as set by John Kerr in 1954 but could not find anything.

1-1974 County Surveyor found McGhie's pipe at the Center 32. Set a 3/4" rod as 1/4 Cor. 29-32 over the pipe at the Center 32 and the line from Sec. Cor. 28-29-32-33 to Section Cor. 29-30-31-32 after much probing and digging. The corner came 11.1 North and 3.2 East of a rod set by the M.H.D. and under the N-S fence.

3-29-1979 County Surveyor visited the corner and found the 3/4" rod set in 1974 which checked with reference point. Set a C.I.M. over the rod and drove a post with survey marker sign 1 foot west of the C.I.M. and took an additional reference point.

2-22-1984 County Surveyor found CIM in good condition.

2-8-2002 County Surveyor visited area of corner. Corner destroyed due to new subdivision.

8-23-2007 County Surveyor visited area, did not find anything.