Certificate of Location of Government Corner

ID#: 742906 **Description:** 1/4 SEC COR 29 30 74 **Date Set:** 7/11/2008 **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2 1/2' south of centerline of E-W twp road, 3 1/2' east of centerline of twp road north and in line with fence south
County Survey Disk in PP #51108 S 28.08'
3/4" iron pipe under fence S 100.20'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, M. Karrick, 40.00 set 1/4 section on post in mound, trench, pitts, charred stake & Osage Orange seeds NE & SW.

8-1857 T. Hunter, P.36, No.58 Used corner, meas. west to center 19.70 (1300.2' M&L then 20.00 (13.20' then 18.10 (1194.6' to W1/4 Cor.

4-1858 T. Hunter Pg.52 No.75 - 1/16 East 19.91 chs. M&L to Center section 29, meas. north 39.70 chs. to sec. cor. (See survey for breakdown of No. 1/2 sec. 29).

1941 J. Kerr, B.25, P.36 Found limestone 4x10x15 - 726.8 North of R.R., set pipe 100' so. (3/4"). 729.0 Hunters tie to centerline.

9-1961 J. Kerr set CIM with iron below., 3/4" pipe in fence line south, Sp in fence post NE 45.24.

10-1961 J. Kerr B.84, P.23 Meas. from E1/4 31 North to limestone in order to set sec. corners 29-30-31-32 which was in enormous hedge of throng brush and was lost total mile.

Feb 1974 County Surveyor reset a nail from Rp's above, Cascade Twp. paved road etc. & monu. very deep.

2-14-1984 County Surveyor found nail in blacktop which checked with Kerr R.P. pipe to south (1961).

2-21-1984 County Surveyor found 1974 P.K. set by C.S. 1.34 East of nail found 2-14-84. Set 3/4" re-rod in place of P.K. corner 21/2' south centerline E-W road and 31/2' East centerline road north and in line with main line fence south.

2-8-2002 County Surveyor found 3/4" rerod down 0.3' in good condition.

2-14-2002 County Surveyor removed 3/4" rerod and set 1" square pipe w/cap at surface.

5-29-2008 County Surveyor found 1" square pipe without cap at surface badly mangled.

7-11-2008 County Surveyor found 1" square pipe w/out cap down 0.3' w/top mangled. Took local ties and removed. Set 1" square pipe w/cap at surface.