Certificate of Location of Government Corner

ID#: 743006 **Description:** W 1/4 SEC COR 30 74 **Date Set:** 8/6/2007 **County:** Olmsted

Section: 30 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 44, in centerline of CR 156 west and 8' south of centerline of township road east (19th St NW)
The monument is at the surface
County Survey Disc in NE side PP #41607 SE 54.76'
"X" nails in SE face of PP NNW 213.17'
This corner is located by GPS measurement

Corner History:

10-4-1853 John Ball, Deputy Surveyor, measured north 40.00 chains between Sections 25 and 30. Set post and drove charred stake for quarter section corner. Built mound and dug trench per instructions. Planted Osage Orange seed SE and Apple seed NE.

8-21-1857 Thomas Hunter, (Book A, Page 36, Survey No. 58), used quarter post.

8-24-1857 E.P. Bircher, by Thomas Hunter, Deputy, (Old Road Book, Page 67, Road No. 71 and New Road Book, Page 172, Road No. 71), used quarter post for road survey.

4-8-1863 P.C. Compton, Deputy County Surveyor, (Book A, Page 72, Survey No. 103), used quarter post.

6-11-1936 County Highway Department, (CHD Book No. 81, Page 24), dug and found nothing.

9-30-1963 John Kerr, County Surveyor, found limestone. Set Cast Iron Monument over limestone. RPs - Center 24' Maple NW 63.0', Center 30" Pine NW 76.6', Nail & Disc in power pole SW 43.35', Nail & Disc in power pole SSE 119.1', Nail & Disc in telephone pole NE 59.2'.

5-1968 County Highway Department, (CHD Book No. 335, Page 3), found Cast Iron Monument. P.I. Sta. 211+01.75. RPs - Spike & Disc in Elm NW 63.06', Spike & Disc in telephone pole NE 59.22', Spike & Disc in power pole SW 43.18'.

6-22-1972 Roger Brand, County Surveyor, remove Cast Iron Monument prior to road construction. Set 1/2"x2' rod. RPs - Bottle cap in top of corner post SW 57.14', County Highway Disc in south side 30" Maple WNW 110.98', Center 5" Walnut NW 130.2' (slope).

8-28-1974 Roger Brand, County Surveyor, found 1/2" rod. RPs - County Highway Disc in SW side power pole #42931 SE 52.43', County Highway Disc in telephone pole NE 59.22'.

10-7-1986 County Survey Crew found 3 different spikes and 3 different rods at various locations. Took local ties and removed all. (See 1986 Remonumentation Book, Page 67).

4-21-1989 County Survyeor Crew found local ties used in 1986. Set 1" square pipe w/cap at surface at deepest monument found location. RP - County Survey Disc in power pole #42391 SE 52.47'.

7-1-1990 County Highway Department found and used 1" square pipe w/cap for CR 156 road alignment. P.I. Sta. 132+53.80.

4-30-1996 Wayne Claassen Engineering & Surveying, Inc. found 1" square pipe w/cap down 0.3' in good condition. The corner falls in centerline of CR 104 and in centerline of CR 156 west.

2-8-2002 County Survey Crew found 1" square pipe w/cap down 0.3' in good condition and measured its position using GPS.

6-27-2002 County Survey Crew found 1" square pipe w/cap down 0.3' in good condition.

5-18-2007 County Survey Crew found 1" square pipe w/eroded cap down 0.3' in good condition. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. Removed 1" square pipe w/cap.

8-6-2007 County Survey Crew set 1" square pipe w/cap at surface from references for 2007 bituminous overlay project. The corner falls in centerline of CR 104, in centerline of CR 156 west and 8' south of centerline of township road east (19th St NW). RP - County Survey Disc in NE side power pole #41607 SE 54.76'.

12-23-2009 County Survey Crew found 1" square pipe w/cap at surface in good condition.