Certificate of Location of Government Corner

ID#: 743304 **Description:** S 1/4 SEC COR 33 74 **Date Set:** 6/17/1964 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 28' south of centerline of Golfview Ln and 27' north of Rochester Country Club Golf Course wooden fence
County Survey Disk in 33" Oak E 10.75'
County Survey Disk in 12" Elm SW 23.29'
Post w/sign 1/2' north
This corner is located by GPS reference stations "Country Club A & B"

Corner History:

10-4-1853 Orig. Gov't Notes Sec. line between Sec. 33 & 4, 40.00 chs. set post for qr. section corner, White Oak 8" S 78°E 16 lks., White Oak 8" S 44°W 19 lks. 68.00 Brook 8 lks. wide runs NE. 80.00 set post & drove charred stake to sections 4-5, 32&33, Built mound.

10-1892 W. Fraser P.495 No.468 (See field notes in Book 8 P.32-37 T.F.) Corner completely gone. Reset corner - set stake with stone by its side. West set stone 4x8x24 at 14.821/2, 16 south 19.57, east 14.871/2 then 9.911/2. then 14.871/2, corner east of 1/16 corner south of N1/4 4.

1941 J. Kerr, Bk. 25 Pg. 68 Plat shows 2" pipe as S1/4 33-107-14, meas. N. 2654.5 - meas. west 2619.2'.

6-17-1964 J.Kerr set CIM over 5/8"x10" rod.

9-15-1978 W. Fraser's Prop. corner 14.871/4 chs. east. County Surveyor found W. Fraser's stone with stake or old post on W side under the E-W fence and in line with old fence ridge south.

9-15-1978 County Surveyor at 1/16th corner east. Dug for stake and stone, found nothing.

8-30-1989 County Surveyor found CIM in good condition.

8-15-2002 County Surveyor found CIM at surface in wooded area South of Golfview Ln near Rochester Country Club Golf Course.