Certificate of Location of Government Corner

ID#: 743404 **Description:** S 1/4 SEC COR 34 74 **Date Set:** 11/18/2005 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 14W **Monument Description:** 1" Copper Plug w/punch mark RLS #15809

Reference Ties:

The corner falls 1 1/2' north of centerline of south east bound left turn lane on 2nd St SW and 81' west of centerline of on and off ramps for south bound TH 52
This corner is located by GPS measurement

Corner History:

Gov't Notes - 40.00 sec. post for 1/4 sec. corner, Burr Oak 10 S 5 E 84, Burr Oak 8 N 401/2 E 94.

12-17-1874 T. Hunter, Field Book 4, P. 14-15, quarter post missing but found stone planted in middle of road by Mr. Mussan and others averred where quarter post stood. Tested stone with northeast bearing tree, still standing, and found it correct.

10-6-1892 T. Fraser, P.495, No.468 Found stone set & recorded by Hunter, 16 west set stake M&L 20.021/4, 16 south found stake by Hunter set stone 3x11x13.

10-26-1893 W. Fraser, P. 535, No. 497, found stone in corner of road.

1969 Corner now large solid rod likely 7/8" put in by state when road or street repaved correct.

7-1975 Fraser Co. removed concrete pavement so looked for stone. Found nothing.

10-9-1986 County Surveyor found rod as described.

7-18-1989 County Surveyor found iron rod in 2nd St. S.W. located corner in city of Rochester mapping project survey.

4-6-1999 MN/DOT survey crew found 3/4" iron rod as monument of record and measured new reference ties.

3-5-2002 MN/DOT survey crew found iron rod in good condition.

8-1-2002 County Surveyor found iron rod in good condition at surface. Set 2 points and tied out corner for Hwy 52 construction.

11-18-2005 County Surveyor set 1" copper plug w/punch mark at surface from 2002 construction tie-out.

8-22-2007 County Surveyor found 1" copper plug w/punchmark at surface in good condition.