Certificate of Location of Government Corner

ID#: 750104 **Description:** 1/4 SEC COR 1 12 75 **Date Set:** 9/6/2005 **County:** Olmsted

Section: 01 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' north of centerline of E-W twp road and 8 1/2' west of centerline of field entrance south
Bottle cap in S side PP #40587 ENE 74.28'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, Karrick; 40.0 set temp 1/4 section post west on true line between section 1 & 12 V9° 5'. 40.0 set 1/4 section post in mound with trench, pits, charred stake, and osage orange seed NE & SW.

6-1870 Perry, Bk.A Pg.122; Found the stake standing and set a stone 2 1/2"x7"x27". Sixteenth stone east at 1314.06'.

6-1873 T.Hunter, Bk.A Pg.232; Found the stone and the sixteenth stone east.

6-1930 J. Kerr, Bk.3 Pg.40, found the stone.

11-11-1971 County Surveyor found rod set by McGhie. Took measurements in area.

5-26-1972 County Surveyor set CIM over the stone. RPs-Corner 3.6' north & 2.65 east of McGhie rod, Corner 3.5' north center of road and 2.5' east of fence south, sixteenth iron set midway & on line East 1311.85'.

7-6-1999 County Surveyor found CIM with head broken off down 0.8'

3-23-2004 County Surveyor found CIM without head down 0.8' in good condition.

9-6-2005 County Surveyor found CIM without head down 0.9' in good condition. Removed CIM and found 2"x7"x27" stone down 2.6' in good condition. Removed stone and set 5' telspar pipe w/cast iron cap down 0.4'.