Certificate of Location of Government Corner

ID#: 750205 **Description:** SEC COR 2 3 10 11 75 **Date Set:** 9/6/2005 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of E-W twp road, 2' east of fence north and 15' west of centerline of residential driveway south
Small chisel cut on top center of east end of 15" CMP WSW 103.08'
Capped pipe set as property corner NNW 32.53'
County Survey Disk in PP #48490 NNW 25.34'
This corner is located by GPS measurement

Corner History:

L* 1-1872 T. Hunter, Bk.A Pg.192; Found the stub of a stake with all the bearing trees, renewed the stake.

1-1882 T. Hunter, Bk.A,Pg.371; Found the corner post of the fences N and E checking with the stumps of the bearing trees.

12-1893 W.Fraser, Bk.A Pg.540; Found the post planted as the section corner and tested it by the witness tree and the stump of the tree taken in 1882.

9-11-1972 County Surveyor found the bottom portion of a 10" diameter post which checked with the measure and line from the east. Set 1 1/4"x2' galv. pipe over angle iron with CIM on top.

11-13-1975 County Surveyor dug 8' x 10' hole with tractor at 1/16 corner West, did not find WCF stake. Dug also at 328.18 N for stone but found nothing (in field).

8-23-2005 County Surveyor found CIM down 1.4' in good condition.

9-6-2005 County Surveyor removed CIM and found 1 1/4" pipe down 3' in good condition with angle iron inside. Removed pipe and angle iron and set 5' telspar pipe w/cast iron cap down 0.4'.