Certificate of Location of Government Corner

ID#: 750505 **Description:** SEC COR 5 6 7 8 75 **Date Set:** 10/12/2006 **County:** Olmsted

Section: 05 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Spike in 12" Maple SSW 23.72'
Post w/sign 2 1/2' north
This corner is located by GPS reference stations "Buckwalter C & H"

Corner History:

Gov't Notes: Set post for corner to sections 5-6-7-8. Ironwood 8" S 22° W 14 lks. Sugar 18" N 83° W 58 lks. Walnut 16" N 18° E 42 lks. Elm 12" S 18° E 68 lks (accepted as B tree 1974). Land rolling and second rate timber Aspen and Oak.

8-1974 County Surveyor-corner falls in a very wet area, springs all over. Impossible to dig for corner. Ran traverse (electronic) to corner location to try and isolate corner. Found all fences led to a large Elm. Used Elm as a gov't B tree and with transit compass we established point. Also check gov't distance to a creek 0.7 chs (46.2) North. Checked within 1 ft. The lost position of the corner is set by double proportionate measure would place corner 3' West and 15' North of our point making a larger kink at 1/4 cor 5&8 as line from NE 8 over N 1/4 8 already falls South. Accepted large Elm (± 40" dia) as gov't B tree, set corner. RP's: Spike in maple SSW 23.5'. Spike S side Walnut W 14.92'. Spike W side Elm S 18° E 45.1'.

10-27-2003 County Surveyor found 1/2" rerod laying on the ground. Found spike in Maple SSW in good condition. Other ties gone.

10-12-2006 County Surveyor set 5' telspar pipe w/cast iron cap up 1' from GPS and traverse data. Set post w/sign.