Certificate of Location of Government Corner

ID#: 750506 **Description:** 1/4 SEC COR 5 6 75 **Date Set:** 10/28/2003 **County:** Olmsted

Section: 05 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of N-S fence and in line with fence west
Post w/sign 1' West
This corner is located by GPS reference stations "Kunkel A & B"

Corner History:

1854 Gov't Notes Karrick 40.00 set temp 1/4 section post South on true line between section 5&6 40.15 set 1/4 section post. Black Oak 6 N 50 W 36. White Oak 18 S 13 E 108.

4-13-1971 County Surveyor, Gov't records from 1/4 5-6 North to N 5-6 S 1/2 1320 20 chs N 1/2 20.14 1329.24. Meas from rod set N 5-6 South, found 1/16 fence West at 1351.0 (R1329.24). Found 1/4 fence West at 2680.0 (R1320) 2649.24. Common land on East side of line South above corner so fences as in place only witness to possible corner. Corner area on steep wooded slope. Limestones in area. Set slim limestone vertically East of corner post also wood stake by stone, very wild rugged area.

3-24-1988 Vince Fangman set 1/2" pipe just to the West edge of small stone set by R.B. in 1971. Corner 1' East of corner post. Set stubbed T steel post 1.0' SW. RP's 31.08 to 30d nail in 6" Elm NNW. 10.60 to 30d nail in 24" Black Oak SW. 21.59 to 30d nail in 6" Cottonwood NE. Drove 30d spike in the South face of a 24" White Oak ± 80 North for site only (State plane bearing to tree from corner N 00° 47' 31" E).

10-27-1988 County Surveyor visited corner location to look for witness trees and look at the fence intersection where R.B. set his stone in 1971. V.F. pipe w/cap is on W edge of Roger's stone. There were no trees that matched the bearings and distances.

10-28-2003 County Surveyor found 1/2" pipe w/cap up 0.2' in good condition. Removed 1/2" pipe and 1"x3"x12" stone. Set 5' telspar pipe w/cast iron cap up 0.2'. Set post w/sign 1' West.