Certificate of Location of Government Corner

ID#: 750509 **Description:** SEC CEN 5 75 **Date Set:** **County:** Olmsted

Section: 05 **Township:** 107N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

Reference Ties:

The corner falls 6 1/2' south of centerline road & 13' east of fence line south
Spike in PP #22755 northerly 35.74'

Corner History:

1-1870 R. Perry (P.95 No.139) found stake standing section sub-divided previously. Set new stake, walnut marked on all 4 sides. 22" Walnut N 45-1/2° W 11 lks blazed 7.26'. 18" Red Elm N 48-3/4° E 50-1/2 lks blazed 33.33. Near root and well above ground. Meas South set K 5.62 370.42 North of 47 which was placed 1320' North of 1/4 5-8 a post found, caption later by W.Fraser 1901 as a stone. East put a walnut post marked at 660' then 742.5' to H a walnut post found with piece in ground set 4" square post marked. RP's: "H" 24" Elm N 75-1/2 E 14.52. "A" 20" Black Oak N 60-1/2 E 30.03. "D" 24" W Oak N 70° W 11.22 marked near root of tree.

? W Fraser; meas. South set K 5.62(370.42 north of 47 which was placed 1320' north of 1/4 5-8 a post found (caption later by W Fraser 1901 as a stone-east a put walnut post not markes at 660' then 743.5' to H a walnut post found with piece in ground set 4" square post marked. RPs-H 24" elm N75 1/2 E 14.52, A 20" black oak N60 1/2E 30.03, D 24" w. oak N70°W 11.22 marked near root of tree.

1970 Sankstone set 5/8" rod supposedly set correctly by inter lines. RPs- spike in fence post SW 26.74, spike in pp northerly 35.74, corner lies 6.5' south of centerline road & 13' e of fence line south.

3-28-1990 V. Fangman found 5/8" iron rod at center of section.

9-15-1998 V. Fangman found 5/8" iron rod at center of section. He use corner for survey in NE & NW 1/4 section 5.

1-30-2006 County survey crew visited the area of the corner. Found nothing.

4-26-2007 V. Fangman used computed location at center of section 5.

2-21-2013 County survey crew searched for Sankstone's 5/8" iron rod. Found nothing.