Certificate of Location of Government Corner

ID#: 750604 **Description:** 1/4 SEC COR 6 7 75 **Date Set:** 10/7/2003 **County:** Olmsted

Section: 06 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fences south and east
Sign on CP 1' south
This corner is located by GPS reference stations "Buckwalter G & H"

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor; West between sections 6 & 31. 40.00 chs set temp quarter section post S 89º 51' E on a true line between sec. 6 & 7, 38.90 set 1/4 sec. post. RPs; 8" black oak N 35º E to links, 6" Burr Oak S 45°W 37 lks. 50.00 chs enter timber bears NW, 79.50 chs to township corner.

2-1871 Robert Perry, County Surveyor, found original stake standing.

10-1964 J. Kerr set 1 1/4"x4' pipe thru old stake or post remains found.

3-10-1977 County Surveyor found Kerr's 1 1/4" on the north side of a new corner post to fences South and East.

10-7-2003 County Surveyor found 1 1/4" pipe up 0.2' in good condition. Removed pipe and set 6' telspar pipe w/cast iron cap up 0.2' at pipe position. Set sign on CP.