Certificate of Location of Government Corner

ID#: 750706 **Description:** W 1/4 SEC COR 7 75 **Date Set:** 1/31/2012 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 15W **Monument Description:** 5/8" brass plug with punch mark

Reference Ties:

The monument is at the surface
The corner falls in centerline of CSAH 5
1" square pipe with cap E 74.83'
1" square pipe with cap W 74.41'
County highway disk in PP #51179 NW 68.53'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor; North between sections 7 & 12. 40.0 set quarter section post and made trench. RPs-14" black oak N0°15W 1016 links

4-1897 William Fraser (Bk. A Pg.607 No.552) states that the corner was gone. Set a limestone as the corner midway and on line.

9-1936 county highway department (county highway department Bk.84 Pg.76)records a boulder stone set for corner.

11-1946 John Kerr (Kerr Bk.32 Pg.43), County Surveyor records a limestone at this corner.

9-1964 John Kerr (Kerr Bk.89 Pg.58-cert. Filed) found the corner. Set a CIM over an iron and the stone. RPs-disc in power pole NW 53.9, west road fence running N & S W 45.3, lies in center of blacktop.

11-5-1978 County Surveyor dug down on the west side of Kerr's CIM (the head was broken so removed it). Found CIM over a pipe driven on the south side of limestone of about 12" length and rectangular shape in black original soil. The stone came just .4'east and .2' south of midway and on line from the SW corner 7 to the stone found at the NW corner 7 in this survey.

5-4-1980 County Surveyor, 1980 Remonumentation Bk; Took references prior to road grading. 1"x35" square pipe with cap 12" deep E 74.83', 1"x35" square pipe with cap 12" deep W 74.41'.

7-11-1985 County Surveyor took additional references; set pk nail 214.29 south of the corner in the centerline crack at the end of previous concrete construction and a line to a 5/8" rerod 429.41 south of the Pk nail (rod 29.3 swly of centerline CR 5 on curve from north to SE and 42.45 NE of the center of pp#47312. Note: line from Pk to rod passed .13 west ofP.T.

8-7-1989 County Highway Department set 5/8" brass plug in centerline CR 5. RPs-county highway department disc in power pole NW 68.53'

12-8-2004 County Surveyor found 5/8" brass plug in good condition.

10-23-2006 County survey crew could not find brass plug. May have been destroyed with concrete milling of CSAH 5. Found reference pipes E & W.

12-12-2007 Vince Fangman could not find brass plug.

1-31-2012 County survey crew set new brass plug with punchmark using the same coordinates as the previous brass plug.