Certificate of Location of Government Corner

ID#: 750709 **Description:** SEC CEN 7 75 **Date Set:** 3/22/77 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1 1/4" pipe

Reference Ties:

The corner falls 13' east of N-S fence and 50' south of centerline of E-W farm driveway
This corner is located by GPS measurement

Corner History:

2-11-1871 Robert Perry, County Surveyor, (Pg.145 No.171) found a stake standing. Set an oak post marked on 4 sides. RPs-14" oak S14°W 51 links 33.66, 7" oak N17°W 29links 19.14.

11-1946 John Kerr, County Surveyor, (Bk.32 Pg.43) records a 1 1/4" pipe as the corner.

9-1964 John Kerr (Bk.89 Pg.58) set a CIM as the corner at intersecting 1/4 lines after resetting the South 1/4 corner 7.

8-19-1974 County Surveyor found Kerr's CIM and also found the 1 1/4" pipe (recorded in 1946) 6.95' east of the CIM.

3-22-1977 County Surveyor accepted the 1 1/4" pipe as the center 7

3-28-1977 County Surveyor removed Kerr's CIM 6.95' West of the pipe.

5-29-1996 V. Fangman found and used 1 1/4" pipe at the center of section.

4-6-1999 V. Fangman found and used 1 1/4" pipe.

10-20-2003 County Surveyor found 1 1/4" pipe down 1.1' in good condition.

12-9-2004 County Surveyor found 1 1/4" pipe down 1.2' in good condition.

3-28-2005 V. Fangman found and used 1 1/4" pipe.