Certificate of Location of Government Corner

ID#: 750906 **Description:** 1/4 SEC COR 8 9 75 **Date Set:** 11/29/2005 **County:** Olmsted

Section: 09 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 11 1/2' east of centerline CR 105 and 4 1/2' south of fence line west
Center punched spud on west side of PP #22792 SSE 127.96'
1/2x24" iron rod placed 4.5 ' south of fence running W 80.15'
This corner is located by GPS measurement

Corner History:

1854 Govt. Notes: Michael Karrick 40.00 set 1/4 sec post Elm 11" S60W 49 links Ironwood 7" S60E 45 links.

6-1900 R.Fraser found wood stake and drove gas pipe as corner . Found this gas pipe this day abd placed CIM over it.

7-1910 Charles Larson Pg.132B; Claims set stone over hole filled with lime at location of stake found at 80 rods s, also stone over lime hole 40 rods south. RPs-11" elm S60° W 217-143.22

11-1960 John Kerr B.80 Pg.57; Didn't look for corner, didn't have notes of gas pipe. Set 1" square steel shallow shaft from old farm machine at 2644.51 from rectangle iron to CIM at 4-5-8-9. RPs-spud in power pole SSE 124.7, disc in treated fence post WNW 49.96, north-south fence on west side of road w 49.0, corner lies 7.6 south of fence running west, corner lies 2.0 east of east edge road surface in edge of ditch. South set 1/2" rod on line as line west at 1222.25 Rp-spike in power pole W of S 24.8'. Set stone 2x12x16 over lime hole 80 rods west.

8-6-1970 County Surveyor set CIM over gas pipe set in 1900. Rps- original spud in pp(west side)#22792 SSE 128.03, 1/2"x2' rerod due west 80.0' rod lies 4 1/2' south of e-w fence and 1.5' north of random steel electric fence post. Corner in line edge of east edge of traveled road.

4-20-1971 County Surveyor found likely 1/16 corner as stone over lime hole. Found some lime and wood stake. Set 1/2"x4' iron rod, stone on east side 3x7x12± and wood on west side.

12-5-1975 County Surveyor set 3/4" x 24" rod at computed M&L location. RP's: Nail E side 24" Oak SSW 21.68. Nail N side 18" Oak WNW 14.90. (center SE 1/4) set 1/2" x 15" rod at (comp) intersecting 1/16 lines. Corner comes in N ditch of E-W road (29' N of centerline). RP's: CSD in most Northerly post of Oxbow park sign WNW 77.77. CSD in PP #22804 SW 88.74.

Note: This corner is a correction of a corner pipe placed in 1960 which we pulled out. Incorrect pipe was 5.65'east and 2.55' south of correct corner.

1-9-2001 County Surveyor found CIM down 1.2' leaning east.

1-18-2001 County Surveyor removed CIM. Found 2" gas pipe down 3.5'. Set 120d spike over gas pipe down 0.2'.

5-26-2005 County Surveyor found 120d spike down 0.3' in good condition.

11-29-2005 County Surveyor found 120d spike down 0.3' in good condition. Set CIC on a 2 1/2' telspar pipe down 0.4' at 120d spike location.

3-1-2010 County survey crew found cast iron cap on telspar pipe down 0.4' in good condition