Certificate of Location of Government Corner

ID#: 751005 **Description:** SEC COR 9 10 15 16 75 **Date Set:** 2/12/2004 **County:** Olmsted

Section: 10 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

60d spike in E side CP for fence south and WNW S 15.20'
Spike in 24" Maple W 25.58'
Spike in N side 30" Elm W 7.63'
Sign in CP 1/2' E
This corner is located by GPS reference stations "Triple Dive A & B"

Corner History:

1854 Gov't Notes: Karrick; 80.00 set cormer section post. RPs- 12" aspen S 51 W 12, 20" maple N 52 W 73, 12" aspen N 67 E 85, 14" aspen S 63 E 22.

11-1887 T. Hunter, Pg.422 No.411; Found old stake in ground, tested stumps of bearing trees, set quarry stone with new stake by side. Measured north 39.94' to stake set this survey from old line east from center over 1/16 corner west. East set stake at 11.63 1/2 then 6.0' then 7.41' then 14.96 1/2. Complicated paoperty survey SW 1/4 10.

10-5-1963 J. Kerr set CIM over rod or concrete cylinder. (Monument could be broken off. RB) RPs-Fence corner post now on east side of monument ± 6", Spike in 24" maple West 25.4', spike in NW side of 30" elm NE 21.10'.

11-7-1975 County Surveyor checked reference ties.

2-12-2004 County Surveyor found CIM with most of body broken off, took local ties and removed. Found concrete monument below CIM down 1.0', removed. Set 5' telspar pipe w/CIC down 0.1'. 60d spike in north side 30" elm 7.63' west and 60d spike in east side of corner post for fence running south WNW 15.20' south. Checked tie to spike in maple 25.58' WSW, elm tree gone. Set sign facing west on corner post for fence running N&E.