Certificate of Location of Government Corner

ID#: 751205 **Description:** SEC COR 11 12 13 14 75 **Date Set:** 2/3/2012 **County:** Olmsted

Section: 12 **Township:** 107N **Range:** 15W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is up 0.2'
The corner falls just north of fence corner and in line of fences N-S-E-W
Sign nailed on SE side of power pole
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 80.00 set post for corner to section 11-12-13-14 and erected mound with trench, pits, charred stake and osage orange seeds at each angle.

5-1870 R. Perry Pg.111 No.148; Found old stake in mound, renewed mound set stone with old stake beside it. 1/16 west found stake, tested it correct, set stone beside it made mound and pits 39.60.

1-1882 T. Hunter Pg.371 No.362; Found stone on south side fence post Pg.111. 1/16 west found stone Pg.111 to be 5 links too far east to be midway set temp stake M & L 19.94 (S89°45'E), 1/16 north set temp stake M & L 19.98 for line center SE 1/4 1318.68 (N38'E), and 1/16 center SE 1/4 11 set stake true inters. lines. Bearing of line west above 1/16 N89°35W.

10-5-1965 J. Kerr set CIM over 1/2"x14" rod with flat rock 3" thick and 6" diameter lying flat on top of rod.

6-8-1972 County Surveyor found 1/16 stone east at 1324.87. Set 1/2"x4' rod.

12-4-1981 County Surveyor, found CIM by Kerr is on the north side of the newest CP. The oldest looking post stands on the east side of this post and leans southeasterly. The next oldest looking post stands on the west side of the newest post and leans southwesterly on the south side of this post and down ± 1 1/2'. We found a 3" piece pf limestone standing, which had been dug in, but since it was not a very large stone and we found no stake we couldn't determine if it was the corner stone or a stone dropped in when the post was set. The stone stands .7' west and.5' south of CIM.

5-13-1997 Vince Fangman found CIM without head leaning. Reset broken CIM over stone.

5-2-2002 County Surveyor found CIM at surface in good condition with head broken off.

2-3-2012 County survey crew found cast iron monument with top broken. Removed CIM and found stone and 1/2" rod directly below. Set 4' telspar pipe with cast iron cap over the found 1/2" rod.