Certificate of Location of Government Corner

ID#: 751305 **Description:** SEC COR 13 14 23 24 75 **Date Set:** 5/3/2004 **County:** Olmsted

Section: 13 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

This corner falls 1' west of centerline of N-S twp road, 1' north of fence east and 17' south of centerline of driveway west
NE corner house SW 89.6'
Split in center west headwall culvert SW 21.6'
NW corner of house foundation SW 113.85'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 80.00 set post for section corner 13-14-23-24. Erected mound with trench, pits, charred stake, and planted osage orange seeds at each angle.

1880 T. Hunter, unrecorded Pg.111 No.358 old courthouse book; found old stake, set stone 2x4/6x26. Set 1/16 south 5x5x16 stone.

1965 John Kerr set 120D on measure from west and line from north at NW corner 13 accepted for survey tract of land south of blacktop in NE 1/4 of SE 1/4 section 14.

8-1967 John Kerr set CIM in place of 120D over 1 1/4x18" pipe. RPs-Center 24" burr oak 50 south of west 49.5, NE corner house (old school) SW 89.6, bottle cap east side telephone pole near telephone bell riser SSE 82.45, outside of splice in concrete headwall west end of culvert SW 21.6, corner lies barely north of fence east within 3' of east edge of road.

10-3-1968 John Kerr found stone new RP's.

7-26-1976 County Surveyor took additonal R.P.'s to CIM; NW corner of house foundation SW 113.85, spike in south side of hugh oak with growth on north side SE 161.8

5-3-2004 County Surveyor found 3/4" pipe down 0.7' in good condition. Removed pipe and found CIM down 1.6' in good condition. Removed CIM and found 3/4" rerod down 3.4' in good condition. Removed rerod and set 5 1/2' telspar pipe w/cast iron cap down 0.4' at CIM position.