Certificate of Location of Government Corner

ID#: 751406 **Description:** 1/4 SEC COR 14 15 75 **Date Set:** 7/14/2022 **County:** Olmsted

Section: 14 **Township:** 107N **Range:** 15W **Monument Description:** 1" copper plug with punch mark PLS #18887

Reference Ties:

The corner falls in centerline of CSAH 4
The monument is at the surface
1/2" rod NW 26.11'
1/2" rod SW 27.87'
This corner is located by GPS measurement

Corner History:

5-31-1854 Michael G. Karrick, Deputy Surveyor, measured north 40.00 chains between Sections 14 and 15. Set quarter section post in mound with trench, pits and charred stake. Planted Osage Orange seeds NE and SW.

5-22-1856 E.P. Bircher, by Thomas Hunter, Deputy, (Old Road Book, Page 87, Road No. 7 and New Road Book, Page 74, Road No. 7), used quarter post for road survey.

12-16-1856 E.P. Bircher, by Thomas Hunter, Deputy, (Old Road Book, Page 26, Road No. 26 and New Road Book, Page 108, Road No. 26), commenced road survey 20.00 chains west of quarter post.

6-14-1858 Thomas Hunter, County Surveyor, (Old Road Book, Pages 116-117, Road No. 87 and New Road Book, Pages 193-194, Road No. 87), used quarter post for road survey.

3-17-1873 Thomas Hunter, County Surveyor, (Book A, Page 217, Survey No. 221), "1/4 post missing and ground frozen too hard and deep to dig for the remains of it and being in center of road, doubtful if anything could be found and no one being round who could identify the spot or any (sic) near where it originally stood."

10-29-1879 Thomas Hunter, County Surveyor, (Caption, Book A, Page 217, Survey No. 221), established the corner at the intersection of the line from the East 1/4 corner Section 14 over the center Section 14 and the line from the NE corner Section 15 to the SE corner Section 15.

4-29-1892 Thomas Fraser, County Surveyor, (Book A, Page 482, Survey No. 457), found stone as set by Thomas Hunter.

8-5-1927 County Highway Department, (CHD Book No. 51, Page 71), found stone and spike. RPs - Hub SW 50.2', Hub SW 69.4', Hub SE 50.2'.

1929 County Highway Department, (CHD Book No. 52, Page 8), found stone and spike, P.O.S.T. Sta. 287+33.3. RPs - Hub SW 50.15', Hub SE 50.05'.

5-16-1961 County Highway Department, (CHD Book No. 258, Page 4), 60d spike. P.O.T. Sta. 137+05.86. RPs - Hub NE 40.3', Spike & Disc in telephone pole SE 29.04', Spike & Disc in corner post SW 29.12'.

5-8-1968 John Kerr, County Surveyor, (Kerr Field Book No. 96, Pages 70-71), set 1/2" iron on line from the NE corner Section 15 to the SE corner Section 15 and at Thomas Fraser's measure from the NE corner Section 15. The corner falls 13' east of fence south. RPs - Center of No. plate in power pole #21517 NE 116.7', 3/4" pipe in fence N 49.0'. 1/16th South set 120d spike midway and on line at 1328.54'.

6-3-1976 Roger Brand, County Surveyor, found 1/2" rod. Removed 1/2" rod and dug with backhoe for Thomas Hunter's stone. Found nothing.

6-7-1976 Roger Brand, County Surveyor, set Cast Iron Monument over 1"x12" pipe on line from the NE corner Section 15 to the SE corner Section 15 and at prorated Thomas Hunter measure. The corner falls 0.2' south and 0.05' west of 1/2" rod. The corner falls 1/2' south of centerline of CSAH 4. RPs - County Survey Disc in power pole #21518 NW 199.1', County Survey Disc in power pole #21517 NE 116.95'.

5-21-1998 County Survey Crew found Cast Iron Monument down 1' in good condition. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. RP - Ref pipe N 48.44'.

12-11-1998 County Survey Crew set PK nail at surface from references for 1998 bituminous overlay project.

6-9-1999 County Survey Crew set 1" square pipe w/cap at surface over PK nail. The corner falls 1-1/2' south of centerline of CSAH 4 and 175-1/2' east of centerline of farm drive south. RP - County Survey Disc in power pole #21517 ENE 116.92'.

3-29-2004 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.

7-14-2022 County Survey Crew found nothing at corner location due to construction. Set 1" copper plug with punch mark PLS #18887 at its previously GPS coordinate position. The corner falls in centerline of CSAH 4. RPs - 1/2" rod NW 26.11', 1/2" rod SW 27.87'.