Certificate of Location of Government Corner

ID#: 751504 **Description:** 1/4 SEC COR 15 22 75 **Date Set:** 8/31/01 **County:** Olmsted

Section: 15 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2' east of centerline of CSAH 3 and in centerline of twp road west
Nail and disc in PP NW 46.6'
County Survey Disk in PP #41264 SE 43.97'
Punch hole in S end of culvert SW 46.35'
Ref pipe NW 66.04'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 40.00 set a temporary 1/4 section post west on true line between sections 15-22 V9°15'. 40.00 set 1/4 section post in mound with trench, pits, charred stake, and planted osage orange seeds NE & SW.

3-1873 T. Hunter, Pg.217 No.221; Corner in 1 1/2' washout in road. Set temporary stake midway only 39.95'. 1/16 east set stake midway 19.97 1/2 to stake in mound at SE corner 15.

1927 county highway department Bk.51 Pg.69; No stone, corner assumed to be in middle of road. RPs- Spike in 10" oak NW 81.3', Spike in 12" oak NW 58.3', & Spike in corner fence post E 25.4'

4-23-1969 J. Kerr set short CIM midway and on line between section corners.

6-4-2001 County Surveyor found CIM in good condition. Set 1" square pipe w/cap as ref pipe for 2001 overlays. Tied out corner and removed CIM.

8-30-2001 County Surveyor set pk nail at surface from 2001 overlay tie out.

8-31-2001 County Surveyor set 1" square pipe w/cap at surface.

8-19-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-29-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.