Certificate of Location of Government Corner

ID#: 751505 **Description:** SEC COR 15 16 21 22 75 **Date Set:** 8/23/2005 **County:** Olmsted

Section: 15 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of centerline of E-W twp road and 1' east of centerline of residential driveway south
Punch hole top center 30" CMP ENE 140.00'
County Survey Disk in PP #40804 NW 122.10'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick 80.00 set post for corner to sections 15-16-21-22. Errected mound with trench, pits, charred stake, and osage orange seeds at each angle.

5-1872 Thomas Hunter (Pg.197 No.207), County surveyor, couldn't find the corner. Set a boulder as the corner on the testimony of local residents. Set a stake at the 1/16 south midway and on line.

3-1873 T. Hunter, Pg.217 No.221; found boulder Pg 197.

4-1969 John Kerr (Bk.98 Pg.49-50), county surveyor, dug for the corner, but found nothing. Doubled line and measure from 1/4 corner 21-22 over a stake with harrow tooth beside it found at the 1/16 north and set a CIM over a 1 1/4"x2' pipe as the corner.

6-8-1976 County Surveyor dug with backhoe for Hunter's boulder, but found nothing. Accepted Kerr's location as the corner and set a CIM over a 3/4"x15" pipe driven into a larger pipe as the corner.

5-22-1986 County Surveyor found CIM down 7" head broke 1' S of centerline E-W rd CSD in E side of CP N 32.62'

3-17-2004 County Surveyor found CIM with head broken off down 2' in good condition.

8-23-2005 County Surveyor found CIM without head down 1.9' in good condition and removed. Found 3/4" pipe down 3.4' in good condition and removed. Found 1 1/2" pipe down 4.3' in good condition and removed. Set 7' telspar pipe w/cast iron cap down 0.4' at pipe position.