Certificate of Location of Government Corner

ID#: 751506 **Description:** 1/4 SEC COR 15 16 75 **Date Set:** 7/13/2022 **County:** Olmsted

Section: 15 **Township:** 107N **Range:** 15W **Monument Description:** 1" copper plug with punch mark PLS #18887

Reference Ties:

The corner falls in centerline of CSAH 4 and in line with fence south
The monument is at surface
1/2" rerod NW 26.96'
1/2" rerod NE 40.43'
This corner is located by GPS measurement

Corner History:

6-1-1854 Michael G. Karrick, Deputy Surveyor, measured north 40.00 chains between Sections 15 and 16. Set quarter section post in mound with trench, pits and charred stake. Planted Osage Orange seeds NE & SW.

6-14-1858 Thomas Hunter, County Surveyor, (Old Road Book, Pages 116-117, Road No. 87 and New Road Book, Pages 193-194, Road No. 87), used quarter post for road survey.

5-16-1961 County Highway Department, (CHD Book No. 258, Page 3), 60d spike. P.I. Sta. 84+18.47. RPs - Spike & Disc in telephone pole NW 39.18', Spike & Disc in fence post SE 43.87', Spike & Disc in fence post SW 43.40'.

4-11-1973 Roger Brand, County Surveyor, survey drawing for Daley property shows found 3/4" pipe. The corner falls in centerline of CSAH 4 and in line with fence south (assumed quarter corner).

11-13-1973 Yaggy Associates, Inc. found and used iron monument for the plat of Daley's Second Subdivision.

9-10-1981 Thomas Taylor Co. found and used 3/4" pipe.

9-17-1986 Vince Fangman found and used 3/4" pipe.

5-21-1998 County Survey Crew found 3/4" pipe down 0.3' in good condition. The corner falls in centerline of CSAH 4. Set 1" square pipe w/cap as reference and Referenced corner prior to cold recycling bituminous project. RP - Ref pipe WSW 281.68'.

12-11-1998 County Survey Crew set PK nail at surface from references for 1998 bituminous overlay project.

6-9-1999 County Survey Crew set 1" square pipe w/cap at surface over PK nail. The corner falls in centerline of CSAH 4 and in line with fence south. RP - County Survey Disc in corner post S 50.22'.

2-11-2004 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.

7-13-2022 County Survey Crew found nothing at corner location due to construction. Set 1" copper plug with punch mark PLS # 18887 at its previously GPS coordinate position. The corner falls in centerline of CSAH 4 and in line with fence south. RPs - 1/2" rerod NW 26.96', 1/2" rerod NE 40.43'.