Certificate of Location of Government Corner

ID#: 751605 **Description:** SEC COR 16 17 20 21 75 **Date Set:** 4/19/2004 **County:** Olmsted

Section: 16 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3 1/2' west of centerline of N-S twp road and 5' north of fence east
County Survey Disk in PP #49432 ESE 40.85'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 80.00 set post for corner to sections 16-17-20-21 and erected mound with trench, pits, charred stake, and planted osage orange seeds at each angle.

5-1874 T. Hunter Pg.253 No.253; Corner gone. Measured N 1/4 20 to n 1/4 21 and set temp stake M & L, measured SE 20 to E 1/4 20 and like distance north and set stake as section corner at intersecting points. 1/16 west set stake M & L 19.90 1/2 line south.

6-1885 T. Hunter Pg.397 No.387; Corner gone. (Pg.253) Set stone on north embankment road at point which David King, a homesteader avers it lay .33' south rail fence north still in place. 1/16 north set stone M & L 19.96 1/2.

4-1911 Charles Larson Pg.152B; Found limestone corner. Measured west 39.88' to corner found, and measured south 39.93 to fence line west.

8-27-1965 John Kerr; Found stone 4' down. Set 1 1/4"x10" pipe over limestone with CIM on top. RPs- Nail disc in north side power pole ESE 43.35, center of traveled road lies e 4.5', and fence line running east S 6.5'.

4-16-2004 County Surveyor found 1/2" pipe w/cap RLS 14888 down 0.4' in good condition. Removed 1/2" pipe and found CIM with broken head down 1.3' in good condition.

4-19-2004 County Surveyor removed CIM without head and found 1 1/4" pipe down 3' in good condition. Set 20" CIM over 1 1/4" pipe down 0.2'.