Certificate of Location of Government Corner

ID#: 751606 **Description:** 1/4 SEC COR 16 17 75 **Date Set:** 4/19/2004 **County:** Olmsted

Section: 16 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fences north and east
120D spike in 20" Oak 2' above ground W 47.3'
Post w/sign 2' south
This corner is located by GPS reference stations "Quam C & D"

Corner History:

1854 Gov't Notes: Karrick; 40.00 set 1/4 section post in mound with trench, pits, charred stake, and osage orange seeds NE & SW

6-1885 T. Hunter Pg.397 No.387; Found stone set in mound still plain, from original stake. 1/16 south set stone M & L 19.96 1/2

1890 J. Fraser: Unrecorded survey, found stone, no description. Set stone south M & L 19.96 1/4 1317.5, 2635.0. Set stone north M & L 1314.55

8-26-1965 J. Kerr set CIM over 3/4"x14" iron with stone south of corner. RPs- 1 1/4" conduit pipe up 18" SW 0.7', 40D in each side box elder up 4' S 16.75', 120D in 20" oak on south side up 2' W 47.3'.

12-9-1970 County Surveyor took measurements.

12-4-1975 County Surveyor (1/16 N) Dug 3' x 5' at computed corner location. Covered line from both theoretical location and final location of sec. cor. 8-9-16-17 to North. Found nothing.

4-19-2004 County Surveyor found broken CIM down 0.5' in good condition. Removed broken CIM and found 3/4" iron down 1.5' in good condition. Set 7' telspar pipe w/cast iron cap at surface over 3/4" iron. Set post w/sign 2' south.