Certificate of Location of Government Corner

ID#: 751704 **Description:** 1/4 SEC COR 17 20 75 **Date Set:** 3/12/81 **County:** Olmsted

Section: 17 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 33' west of centerline of CSAH 5, 10 1/2' west of TBC and 5' north of south end of curb
County Survey Disk in PP #22098 SW 101.52'
1" square pipe w/cap W 163.36'
1" square pipe w/cap W 312.26'
This corner is located by GPS measurment

Corner History:

6-1854 Gov't Notes: Michael Karrick, Deputy Surveyor; West on true line between sections 17 & 20. 40.00 chs set quarter section post in mound with trench, pits, charred stake, and osage ornage seeds NE & SW. 80.00 chs section corner.

12-16-1856 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Book--Old Road No.26) surveyed a road on the section line between sections 17 & 20.

10-28-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy, (Old Road Book--Old Road No. 98) surveyed a road on the section line between sections 17 & 20.

1-1869 Robert Perry possibly used this corner to set the Center 17. (See Bk.A Pg.94, Survey No. 138)

1-1870 R. Perry, County Surveyor, (Bk.A Pg. 94 No.138) found center 17 from bearing tree said taken in January, 1869. He used the center to set the 1/16 north midway (19.88 chs) and on line.

1-1871 R. Perry, (Bk.A Pg.141-143 No. 169) set a temporary point at the 1/16 north of the center 17 from bearing trees taken in a previous survey.

5-1874 Thomas Hunter, County Surveyor, (Bk.A Pg.253 No.253 and Old Fieldbook 3 Pg. 101) "Found stone set in center of road as 1/4 post; both bearing trees". He used this corner to set the 1/16 east, a stake, midway (19.90 1/2 chs) and on line, and the 1/16 south, a 18"x6"x2" stone, midway (20 chs) and on line to a stone found at the center 20 set by Perry". Measured 40.12 chs west to the NW corner 20.

6-1885 Thomas Hunter (Bk. A Pg.397 No.387) "found stone set in center of road". He used this corner to set the 1/16 north, a stone in the center of the road, midway (19.89 1/2 chs.) and on line to the center 17 where he found Perry's stake set in Survey No. 138 (Planted quarry stone in place of stake.

4-1911 Charles Larson, County Surveyor, (Bk.B Pg.152) "found corner". Measured 39.88 chs east to limestone found at section corner 16-17-20-21 and 40.12 chs. West to a limestone found at section corner 17-18-19-20. He set a 3"x18"x14" limestone at the 1/16 south midway (20.00chs) and on line to a 4"x16"x20" limestone he found at the center 20.

9-1936 county highway department (county highway department Bk.84 Pg.72) found pointed limestone.

7-1970 County Surveyor, dug and found three 10" bridge spikes (at various depths) set over a 2"x8" topped limestone 4.3 deep. Set CIM over a 5/8"x2' rod inside iron plate(sawed off tamper) over the stone.

6-2-1980 County Surveyor removed CIM for road grading and took reference points.

3-12-1981 County Surveyor set CIM over the sawed off tamper (5/8" rod gone) and checked with references taken 6-2-1980.

4-16-2004 County Surveyor found CIM down 0.7' in good condition.