Certificate of Location of Government Corner

ID#: 751705 **Description:** SEC COR 17 18 19 20 75 **Date Set:** 12/20/2004 **County:** Olmsted

Section: 17 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' east of fence south and under the east-west fence
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 80.0 set post for corner to section 17-18-19-20. RPs- 8" burr oak S87 W 190 links, 6" burr oak S24 E 108 links. Dug trench.

6-1895 W. Fraser Pg.578 No.528; Found marked stake set stone 3x12x24 on east side stake. Measured west 39.66 to stone set this survey.

4-1911 Charles Larson Pg.15e B; Found limestone as corner Pg.578, measured east 40.12' to corner found.

1936 county highway department Bk.84 Pg.74; Found limestone at fence corner.

9-1964 John Kerr; Set CIM in place of original stone by corner post. RPs- corner lies 1.5' east of fence running south and corner post, corner lies under east-west fence, measured south to 1/4 corner 2632.8.

12-9-2004 County Surveyor found CIM at surface leaning southerly.

12-20-2004 County Surveyor took ties to leaning CIM. Straightened CIM and took ties again. Removed CIM and found 5/8" rod slightly leaning SW. Took ties. Removed rod and set 5' telspar pipe w/CIC at straightened CIM location.