Certificate of Location of Government Corner

ID#: 751904 **Description:** 1/4 SEC COR 19 30 75 **Date Set:** 5/16/2002 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with E-W fence and 1 1/2' east of fence south
Post w/sign 2' South
This corner is located by GPS reference stations "Shady Tree A & B"

Corner History:

1854 Gov't Notes: Karrick; 40.0 set temp 1/4 post S89 °45'E on true line between sections19 & 30. 38.75 set 1/4 section post. RPs-10" burr oad S72 W 195 links,12" burr oak N73 W 279.

6-1895 W. Fraser (Pg.578 No.528) Found stake by corner post averred by Mr. D.T. Tompkins. Drove new stake and set stone 6x8x18 by its side.

10-1964 John Kerr; Went to set CIM and found enormous willow tree split and spread out over corner. Stone probably in root system. Recommend burning.

7-22-1997 Vince Fangman, willow tree which was previously on top of corner has fallen and stump rotted out. Set 1/2"x42" (spliced pipe w/1/2" ro) in place of 4"x8"x18" broke stone. Layed 3 pieces of stone around pipe.

5-16-2002 County Surveyor found 1/2" pipe in good condition. Removed pipe and replaced with 5' telspar pipe w/Cast Iron Cap.