Certificate of Location of Government Corner

ID#: 751906 **Description:** W 1/4 SEC COR 19 75 **Date Set:** 10/23/2007 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 7' south of centerline of E-W twp road and 2' west of centerline of twp road south
County Survey Disk in NW side PP #43653 ENE 106.51'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes 40.00 marked on aspen 4"x20" in diameter for quarter section corner. RPs-6" black oak W 9 links, 6" black oak S 20° E 18 links.

6-1895 W Fraser, Pg.578 No.528; Found stone 4x12x18 in center road and location of SE bearing tree stump just grubbed out, proved correct. Set marked stake by stone.

9-19-1964 J. Kerr set CIM over 1 1/4"x10" pipe over stone. RPs- 120D in 14" spruce tree NNE 42.7' disc in power pole ENE 106.3'

6-18-1996 Olmsted County Surveyor found 3/4" pipe above CIM. Drove 3/4" pipe with plastic cap #15809 deeper in road bed. CSD in PP #42653 ENE 106.45'. This corner falls in centerline 19th Ave NW and 5 1/2' south of centerline E-W 23rd St NW.

12-9-2004 Olmsted County Surveyor found 3/4" pipe down 0.3'.

3-24-2006 Olmsted County Surveyor found 3/4" pipe down 0.2' in good condition. Removed pipe and found CIM down 1.1' in good condition. Found 3/4" pipe to be 0.28' east of CIM.

10-23-2007 Olmsted County Surveyor found CIM down 1.1' in good condition. Removed CIM and found 1 1/4" pipe down 2.9' in good condition. Removed 1 1/4" pipe and round 4" x 12" stone down 3.5' in good condition. Removed stone and set 4' telspar pipe w/cast iron cap down 0.4' at CIM position.

1-27-2010 Olmsted County Surveyor found cast iron cap on telspar pipe down 0.4' in good condition.