Certificate of Location of Government Corner

ID#: 752304 **Description:** 1/4 SEC COR 23 26 75 **Date Set:** 9/12/2006 **County:** Olmsted

Section: 23 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' south of E-W fence for Kalmar Landfill
This corner is located by GPS reference stations "KLF 65 & 66"

Corner History:

6-1854 Gov't Notes, Michael Karrick, Deputy Surveyor West on true line between sections 23 and 26 40.00 chs. Set quarter section post in mound with trench, pits, charred stake and osage orange seeds NE and SW

5-1872 Thomas Hunter, County Surveyor (Pg. 204, No. 212) Found fence post in center of mound with pits all plain. Chained east 19.87 set stake then 19.87 to section corner (Set stone). Chained west 19.83½ to section (corner stake). Chained south 39.73 to stake set at intersecting quarter lines.

8-1967 John Kerr, County Surveyor (Bk. 96, Pg. 36) measured section line 2621.4' then 2640.8' for a total of 5262.2 no type of corner used recorded.

12-1972 McGhie & Betts set pipe measured east 2632.79', measured west 2628.16'.

6-1986 County Surveyor dug for corner, found McGhie & Betts pipe, found two old post marks.

6-12-1986 County Surveyor set telspar pipe with cast iron cap as corner on line from south quarter corner of section 26 over the center of section 26, and directly east of first post stub found. This location fits Thomas Hunter's overrun of 8' per half mile to the center of section 26 and from NE corner of section 26 over post stub found at the sixteenth corner east of quarter corner.

8-13-2002 County Surveyor found cast iron cap on telspar pipe up 0.6' leaning westerly under E-W fence.

9-12-2006 County Surveyor found telspar pipe w/CIC up 0.3' leaning west, removed. Set 5' telspar pipe w/CIC up 0.5' from reference angle.