# Certificate of Location of Government Corner

**ID#:** 752506 **Description:** 1/4 SEC COR 25 26 75 **Date Set:** 10/25/1991 **County:** Olmsted

**Section:** 25 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe with cap RLS #15809

**Reference Ties:**

The corner falls 2' south of centerline of CR 156 and in centerline of N-S twp road
Punch mark in N end CMP NW 42.64'
Punch mark in N end CMP NE 50.13'
County Survey Disk in SW side PP SE 43.35'
Ref iron SSE 165.15'
This corner is located by GPS measurement

**Corner History:**

1854 Gov't Notes Karrick; 40.00 set 1/4 section post in mound with trench, pits, charred stake, and planted osage orange seeds NE & SW.

4-1863 P.C. Compton Pg.72 No.103 shows 1/4 corner used to set center 25 at intersecting liners.

5-1872 T. Hunter, Pg.204 No.212; Found stone in center road. 1/16 west set stake M & L 19.81 to center 26, a stake intersecting lines.

8-1966 J. Kerr, Hunted for corner , measured south line 26, dug 20' hole with backhoe, found no stone, may have destroyed stake. Found nail driven in at about recorded chainage from center 26. Set pipe, will set CIM when fill settles. RPs- + in end of galv. Culvert SW 30.25 & NW 22.6

8-23-1968 J. Kerr set CIM and took additional RPs- Disc south side of pp# 22215 SE 55.7, disc west side pp brace # 22216 sw 42.6, center 14" maple in yard NE 109.7

11-8-1973 County Surveyor dug with backhoe and found limestone 4x6x16 down 4' with crockery stone. Stone 10.6 east and 7.1 south of Kerr CIM. Pulled CIM and placed over stone and 1 1/4" pipe, removed pipe below old CIM also,

6-16-1986 County Surveyor found two remaining sections of CIM down 3.2', removed and found 3/4" pipe standing good 4' deep. Set new CIM over pipe at road surface, corner 2' S.of centerline E-W road and 1' west centerline N-S road. RPs to CIM - Punch mark in top north end CMP NW 42.64', punch hole in top North end CMP NE 50.13', CSD in SW side power pole SE 43.35'.

10-25-1991 County Surveyor set 1" square pipe with cap in centerline blacktop CR 156 inline of centerline twp roads N-S county highway department. RPs-Iron SSE now 165.15'

6-27-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

12-23-2009 County Surveyor found 1" square pipe at surface in good condition.