Location of Center of Section

ID#: 752609 **Description:** SEC CEN 26 75 **Date Set:** 11/7/1973 **County:** Olmsted

Section: 26 **Township:** 107N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1-1/4" pipe

County Surveyor recommends using the computed intersection of quarter lines for the center of section.

Reference Ties:

The corner falls in centerline of east-west township road (19th St NW) and in line with power pole line south
The monument is down 0.4'
Ground wire on west side power pole #40081 N 36.1'
1/2" rod, up 0.2', S 50'
This corner is located by GPS measurement

Corner History:

5-21-1872 Thomas Hunter, County Surveyor, (Book A, Page 204, Survey No. 212), set stake at intersecting quarter lines. 1/16th East set stake midway and on line at 19.81 chains (1307.46'). 1/16th West set stake midway and on line at 20.02-1/2 chains (1321.65').

5-2-1885 Thomas Hunter, County Surveyor, (Book A, Page 396, Survey No. 386), found stake at intersecting quarter lines. Set stone with horseshoe below as witness. 1/16th West set large boulder stone midway and on line at 19.93-1/2 chains (1315.71').

7-10-1956 John Kerr, County Surveyor, (Kerr Field Book No. 63, Page 69), dug and found small limestone with horseshoe down 2.5'. Set 5/8" rod. RP - 1/2" rod S 50'. 1/16th West found boulder. RPs - 1/2" rod S 50', 1/2" rod W 50'.

7-25-1956 John Kerr, County Surveyor, (Kerr Field Book No. 63, Page 69), set 1/2" pipe in 1-1/2" pipe. The corner falls in centerline of east-west road. 1/16th West reset boulder over 120d spike and iron wire spool.

10-31-1964 John Kerr, County Surveyor, set Cast Iron Monument over 5/8" rod.

11-7-1973 Roger Brand, County Surveyor, found Cast Iron Monument and dug beside it and found 3/4" rod with horseshoe around it and pieces of limestone on east and west sides. Removed Cast Iron Monument and set 1-1/4"x60" pipe with well cylinder at bottom over rod. The corner falls in centerline of east -west township road. RPs - Ground wire on west side power pole #40081 N 36.1', 1/2" rod, up 0.2.', S 50'. 1/16th West found pipe and boulder to be about 3.5' south of east-west quarter line.

6-6-1986 County Survey Crew, 1/16th West found 9"x11"x14" pointed boulder down 1' with 1" pipe 0.6' west.

10-4-1989 County Highway Department, (CHD Book No. 534, Page 12), found pipe. P.I. Sta. 53+52.80. RPs - Spike & Disc in power pole #40081 N 36.1', Spike & Disc in power pole #39956 S 74.3'.

5-13-1991 Vince Fangman found and used 1-1/4" pipe.

5-14-1993 Vince Fangman found and used 1-1/4" pipe.

5-27-1994 Fangman Land Surveying found and used 1-1/4" pipe.

2-3-1998 Wayne Claassen found and used monument.

10-18-2000 County Survey Crew found 1-1/4" pipe down 0.4' in good condition. The corner falls in centerline of east-west township road, in line with power pole line south and 8' west of new fence line south.

8-15-2002 County Survey Crew found 1-1/4" pipe down 0.4' in good condition and measured its position using GPS.

2-22-2017 Joel Thoreson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the 1-1/4" pipe, as located by GPS in 2002, falls 0.15' north and 0.00' west of the computed center.