Certificate of Location of Government Corner

ID#: 752705 **Description:** SEC COR 27 28 33 34 75 **Date Set:** 9/5/01 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' north of centerline of CR 134 and 30' east of field drive north
SE corner foundation of building N 37.22'
Top center of culvert NE 52.70'
County Survey Disk in PP #22421 SW 50.78'
County Survey Disk in PP #22422 NW 54.64'
Ref iron N 41.40'
This Corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: Michael Karrick, Deputy Surveyor; North between sections 33 & 34. 80.0 chs set section post in mound with trench, pits, charred stake, and planted osage orange seeds at each angle.

3-1871 Robert Perry (Pg.154 No.177), County Surveyor found stake.

3-1893 William Fraser (Pg.525 No.177), County Surveyor found squared stake. Set stone 2"x4"x14" on top of a stone 3"x6"x6".

5-1900 Robert Frazer, Pg. 680 No. 605 found squared stake and stone.

5-1963 county highway department Bk. 264 Pg. 1, found stone. Set CIM.

4-6-1976 County Surveyor dug out county highway department CIM and dug down to a 2"x4" topped stone 3' deep. Set a 1 1/2"x1' pipe on the south side of the stone and reset a CIM over the stone at the surface of the road.

6-4-2001 County Surveyor found CIM down 0.2' in good condition. Set 5/8" rerod as ref iron for 2001 overlays. Tied out corner and removed CIM.

8-30-2001 County Surveyor set pk nail at surface from 2001 overlay tie out.

9-5-2001 County Surveyor set 1" square pipe w/cap at surface.

5-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.