Certificate of Location of Government Corner

ID#: 752805 **Description:** SEC COR 28 29 32 33 75 **Date Set:** 3/26/2002 **County:** Olmsted

Section: 28 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2' north of centerline of CR 134 and 25' west of centerline of field entrance north
Nail & disc in TP N 37.68'
Ref iron N 47.21'
County Survey Disk in SE side 8" tree SW 87.74'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick 80.0 set post for corner to sections 28-29-32-33. Erected mound with trench, pits, charred stake, and planted osage orange seeds at each angle.

7-1893 W Fraser, Pg. 525 No.490. Corner gone, dug rod square 2' deep. Run line E 1/4 29 set point midway 39.96 1/2. Run line N 1/4 32 to NE 33 set point 1/3 distance 39.93 2/3. Set stone 5x8x22 which located corner favorably.

1962 county highway department Book 264 Pg.1 found large spike over pointed boulder, hub S 68.3'. Measured west 2633.38, east 5270.34.

6-29-1964 John Kerr set CIM over 1 1/4"x14" pipe.

6-29-1964 J. Kerr at 1/16 corner between SE 29 and S 1/4 29, found stone, set 1/2" pipe on stone (no records). RPs- cross culvert headwall W 21.5', NW corner house SE 42.7'.

6-4-2001 County Surveyor found CIM down 0.6' in good condition. Set 5/8" rerod as ref iron for 2001 overlays. Tied out corner and removed CIM.

3-26-2002 County Surveyor set 1" square pipe w/cap at surface from 2001 overlay tie-outs.

5-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.