Certificate of Location of Government Corner

ID#: 753004 **Description:** 1/4 SEC COR 30 31 75 **Date Set:** 11/16/2004 **County:** Olmsted

Section: 30 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fences N-E-W
Post with sign 1' north
This corner is located by GPS reference stations "Byron Substation A & B"

Corner History:

1854 Gov't Notes Karrick 40.00 set temp 1/4 section post N 84° 52' E on true line between sections 30-31 38.90 set 1/4 section post in mound with trench, pitts, charred stake and Osage Orange seeds NE & SE.

5-1863 P.C. Compton (B.71 No.101) show 1/4 cor (see survey).

5-1870 R. Perry (P.162 No.185 S.29-30-31-32) found original stake in mound and pits.

6-1871 R. Perry (P.168 No.186) used same corner. Stake in mound set nothing no meas from south (meas N 1314.8). 1/16 south set stone 5-1/2 x 5-1/2 x 12 M&L no meas (8-14-70 found meas E 1316.73). 1/16 west set corner at 20.02-1/2 then 18.93-1/2 to sec corner. 1/16 east set stone 3 x 16 x 26 pointed M&L 20.00 (found 6-17-70 meas 1316.0). Hunters RR notes 1555.5 south to centerline RR tracks. Corner found P.168 to be on exact line of north line S.31. Meas west 3894.5 Gov' 38.90.

6-17-1970 County Surveyor meas line from NE 31 west found 1/16 stone as recorded P.162 3' deep 5.7' east of N-S fence 1316.57 west of large pipe at NE 31. Set wood stick over stone which lines fence west quite well. Con't line west to fence line north 1316.0 set lower part of steel post as temp corner about 1' south of large corenr post of good new fence line north.

7-17-1970 County Surveyor measured south found recorded 1/16 stone at 1314.8 meas on W line 1320.67 N-S 1/4 line 1314.8 E line 1310.6 of N line straight as record says N 1/4 iron post would go N 0.83'.

3-21-2000 Brand and Massey Surveying Inc. set 5/8" pipe w/cap at 1/4 corner.

5-21-2002 County Surveyor found 5/8" pipe w/o cap up 0.8' in good condition.

11-16-2004 County Surveyor found 1/2" smooth iron 4' long up 0.6' in good condition. Removed iron and set 5' telspar pipe w/cast iron cap up 0.3' at smooth iron position. Set post with sign 1' north.