Certificate of Location of Government Corner

ID#: 753104 **Description:** S 1/4 SEC COR 31 75 **Date Set:** 6/14/74 **County:** Olmsted

Section: 31 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 5' north of centerline of E-W twp road
Punch hole in E end 18" CMP NE 30.78'
County highway disk in W side CP S 42.34'
Punch hole in W end 18" CMP N 20.63'
County Survey Disk in NW side PP SW 138.15'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: John Ball, Deputy Surveyor; West between sections 6 & 31. 40.00 chs set post and drove charred stake, built mound with trench and planted osage orange SE and apple seed NE.

6-1871 Robert Perry (Pg.168 No.186), County Surveyor set 9"x10"x24" boulder.

10-1884 Thomas Hunter (Pg.393 No.384), County Surveyor found stone.

5-1966 John Kerr, County Surveyor, dug 5' deep in center of road and in line with fence south. Found good portion of stone. Set a CIM over a 1/2"x2' rod. He also set 1/16 west.

6-14-1974 County Surveyor dug at south 1/4 corner 31 and found the correct stone 3' south of the north edge of the road and 2' east of the line of the fence south. Set 3/4'x2' pipe on east side of stone and set CIM with 1/2"x2' rod under it. Corner fell 1.75' east and 5.8' north of John Kerr's corner. We also prorated the west 1/2 mile and corrected John Kerr's rod at the 1/16 corner. East 1/2 mile =2636,21' West 1/2 mile=2579.34'

5-9-2002 County Surveyor found CIM down 0.5' in good condition.

4-19-2011 County survey crew found CIM down 0.5' in good condition