Certificate of Location of Government Corner

ID#: 753206 **Description:** 1/4 SEC COR 31 32 75 **Date Set:** 6/11/2002 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2' south of centerline of Frontage Road NW and 84-1/2' west of centerline of 8th Ave NW
The monument is at the surface
County Survey Disc in west side south sign post NNW 57.79'
County Survey Disc in fiber glass light post NE 60.76'
Top nut fire hydrant NE 91.66'
This corner is located by GPS measurement

Corner History:

6-2-1854 Michael G. Karrick, Deputy Surveyor, measured north 40.00 chains between Sections 31 and 32. Set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE and SW.

5-27-1863 P.C. Compton, County Surveyor, (Book A, Page 71, Survey No. 101), found stake and set 3"x3"x8" stone. He states "the 1/4 stake on the east side is out of line east and north of midway between the section corners." 1/16th North set 2"x5"x10" stone midway and on line. 1/16th South set 1-1/2"x5"x9" stone midway and on line.

5-15-1871 Robert Perry, County Surveyor, (Book A, Pages 162-166, Survey No. 185), set 3"x17"x20" stone with mound and pits. Set 2"x10"x20" witness stone 1 chain (66.00') north. 1/16th North set 2"x14"x28" stone midway and on line.

6-5-1871 Robert Perry, County Surveyor, (Book A, Pages 168-175, Survey No. 186), CORRECTION OF CORNER: Removed stone, witness stone and destroyed mound and pits set 5-1871. Found stone set by P.C. Compton averred placed where original post stood. Set 3"x17"x21" stone at old stone location. Made mound with pits north, south, east and west and set oak post. Set 3"x17"x20" stone as witness 50 links (33.00') south. 1/16th North removed stone and witness stone set 5-1871. Set 2"x14"x28" stone midway and on line at 19.87-1/2 chains (1311.75'). 1/16th South found stone and set new 2"x9"x14" stone midway and on line at 20.05-1/2 chains (1323.63').

8-18-1970 Roger Brand, County Surveyor, set lead plug on line and double the distance from NE Section Corner 31 over 1/16th South. The corner falls 1.87' south of centerline of T.H. No. 14. RPs - Top center MHD R/W marker NNW 52.21', Centerline crack concrete pavement North 1.87'.

3-11-1980 County Survey Crew found lead plug in good condition.

1-20-2000 County Survey Crew found lead plug down 0.3' in good condition.

6-11-2002 County Survey Crew found lead plug down 0.2' in good condition. Removed lead plug and set 1" square pipe w/cap at surface and measured its position using GPS.

7-15-2004 WHKS Survey Crew found monument in good condition with ties all in place as described.