Certificate of Location of Government Corner

ID#: 753304 **Description:** 1/4 SEC COR 33 75 **Date Set:** 5/21/2002 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 8' west of centerline of twp road south and 11' south of centerline of E-W twp road
Nail & disc in guide post SW 29.33'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 40.0 set post & drove 5" charred stake for 1/4 section corner. Built mound with trench and planted osage orange seed SE and apple seeds NE.

7-1873 T. Hunter Pg.233 No.235; Corner gone, set temporary point M & L 40 chs.

10-1919 Bound field book at McGhie & Betts office. See back of blue notebook for copy. Indicates stone found 16" deep; meas. E 2634.6 & N 2622.5 to center 33.

10-1921 Charles Larson Pg.362 B; Corner gone , set stone 3x9x24 M & L 40 chs. 1/16 south set concrete slab 6x10x24 at 19.56 then 20.0 to center 4 a limestone 4x14x15. Also, set limestone south 7x8x14 29.56 from N 1/4 4.

4-1965 John Kerr Pg. 51 B.86; Found stone after much digging & measuring. Set CIM over stone found. RPs- disc in power pole ESE 35.9, disc in power pole WSW 29.5. Corner lies 1'± south of south edge taveled road running west and near west edge road south. Meas. East & west 2639.9, meas.south 2609.0(Recorded 2611.0) to center 4.

9-3-1971 County Surveyor projected line from S 1/4 32 over 1/16 E and S 32-33 to area of S 1/4 33 and found proj. line fell 13.15' N of S 1/4 33.

6-12-1990 County Surveyor found pipe with cap #14888 in SW corner of intersection of twp roads. RPs- CSD in pp#40 ESE 38.90, Old disk in guide post SW 29.32, centerline road south E 8', centerline E-W road north 11'.

5-20-2002 County Surveyor found pipe w/cap down 1.0'.

5-21-2002 County Surveyor removed pipe and found CIM down 2.5'. Removed CIM and set 3' telspar w/Cast Iron Cap down 0.4'.