Certificate of Location of Government Corner

ID#: 753305 **Description:** S SEC COR 32 33 75 **Date Set:** 5/20/2002 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' north of centerline of east-west township road (Frontier Rd SE) and in line with fences north and south
The monument is down 0.5'
County Survey Disc in west side large post S 43.58'
Sign on post 43 1/2' south
This corner is located by GPS measurement

Corner History:

10-6-1853 John Ball, Deputy Surveyor, measured west 80.00 chains on true line between Sections 33 and 4. Set post and drove charred stake. Corner to Sections 4, 5, 32 and 33. Built mound with trench per instructions. Planted Osage Orange seed SE and Apple seed NE.

6-1-1854 Michael G. Karrick, Deputy Surveyor, measured north from post, between Sections 32 and 33, for subdivision of Kalmar Township.

6-7-1854 Michael G. Karrick, Deputy Surveyor, measured north 79.57 chains on random line, between Sections 4 and 5, for subdivision of Salem Township. Intersected north boundary 27 links (17.82') east of post.

9-25-1856 E.P. Bircher, by Thomas Hunter, Deputy, (Old Road Book, Pages 28-29, Road No. 32 and New Road Book, Pages 117-118, Road No. 32), used section post for road survey.

4-20-1861 Samuel McDowell, (Book A, Page 66, Survey No. 93), used section corner for property survey in SE 1/4 Section 32 & NE 1/4 Section 5. No description of monument used.

7-1-1873 Thomas Hunter, County Surveyor, (Book A, Page 233, Survey No. 235), found remains of old stake averred by Mr. Dearborn to be where original post stood. Set 3"x7"x16" stone. The corner falls in centerline of road and in line with old fence south.

6-12-1886 Thomas Hunter, County Surveyor, (Book A, Page 412, Survey No. 401), found stone. 1/16th West found stone midway and on line at 19.92 chains (1314.72').

10-31-1921 Charles Larson, (Book B, Pages 362-363), found 4"x7"x16" limestone.

11-19-1963 John Kerr, County Surveyor, found limestone. Set Cast Iron Monument over limestone. RPs - 1/2" pipe north 33.0', 1/2" pipe south 33.0'.

8-28-1970 Roger Brand, County Surveyor, found Cast Iron Monument.

9-3-1971 Roger Brand, County Surveyor, found Cast Iron Monument. Removed Cast Iron Monument prior to road construction. Set 1/2" rod.

7-6-1972 County Survey Crew found 1/2" rod gone. Set Cast Iron Monument from transit ties and reference pipes.

7-21-1980 County Survey Crew found Cast Iron Monument.

6-12-1990 County Survey Crew found Cast Iron Monument with head broken off in good condition. The corner falls 4' north of centerline of east-west township road. RP - County Survey Disc in west side large post S 43.58'. Sign on post 43-1/2' south.

5-20-2002 County Survey Crew found Cast Iron Monument with head broken off. Removed Cast Iron Monument and 1/2" rerod and set Cast Iron Cap on telspar pipe at Cast Iron Monument location down 0.5' and measured its position using GPS. The corner falls 4' north of centerline of east-west township road (Frontier Rd SE) and in line with fences north and south.