Certificate of Location of Government Corner

ID#: 753306 **Description:** 1/4 SEC COR 32 33 75 **Date Set:** 2/1/2012 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap PLS #42638

Reference Ties:

The monument falls 13' south of centerline of frontage road and in line with the centerline of frontage road entrance
The monument is at the surface
Brass plug at T.H. 14 PI S 92.33'
Center of manhole SSE 6'
This corner is located by GPS measurement

Corner History:

6-1-1854 Michael G. Karrick, Deputy Surveyor, measured north 40.00 chains betwee Sections 32 and 33. Set quarter section post in mound with trench, pits, and charred stake. Planted Osage Orange seeds NE & SW.

5-15-1871 Robert Perry, County Surveyor, (Book A, Pages 162-166, Survey No. 185), found old original post in mound and pits in "perfect state of perservation." Set new oak post and renewed mound by making pits north, south, east and west.

5-3-1882 Thomas Hunter, County Surveyor, (Old Field Book No. 5, Page 137), found stake in mound. The corner falls 11.86 chains south of center of railroad.

6-12-1886 Thomas Hunter, County Surveyor, (Book A, Page 412, Survey No. 401), found corner fence post of fences south and east. Corner post claimed set in center of original mound.

7-25-1893 William Fraser, Deputy County Surveyor, (Book A, Page 525, Survey No. 490), found bottom of post in center of road.

7-11-1957 Ken M. McGhie found and used old corner post for the plat of Skyline Addition.

4-8-1974 County Survey Crew set Cast Iron Monument over 1/2"x20" rod from monuments found for the plat of Skyline Addition. RPs - Chisel "L" in concrete curb WNW 50.72', Back edge of curb N 8.6', Brass plug at T.H. 14 P.I. S 92.33'.

5-13-1986 County Survey Crew found Cast Iron Monument. Set reference pipes and reference corner prior to water and sewer line construction.

5-9-2001 McGhie & Betts, Inc. found 5/8" pipe set by Mike Kleinschmidt at corner location.

6-25-2002 County Survey Crew found 5/8" pipe at surface in good condition and measured its position using GPS.

2-1-2006 County Survey Crew found 5/8" pipe at surface is good condition. The corner falls 13' south of centerline of Frontage Road and 1' west of centerline of approach off T.H. 14. RP - Center of manhole SSE 6'.

10-23-2006 County Survey Crew found 5/8" pipe w/broken cap at surface in good condition. RP - County Survey Disc in west side PP N 33.4'.

2-1-2012 County Survey Crew found 5/8" pipe w/no cap at surface in good condition. Removed pipe and set 1" square pipe w/cap PLS #42638 at surface.