Certificate of Location of Government Corner

ID#: 753404 **Description:** S 1/4 SEC COR 34 75 **Date Set:** 2/11/2009 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is at the surface.
The corner falls 11' south of centerline of CSAH 34 and in centerline of CSAH 3
County Survey Disk in PP #40 ESE 121.16'
Ref iron SW 73.15'
Ref pipe NW 135.27'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 40.00 set post & drove 15" charred stake for quarter section post. Built mound with trench and planted SE osage orange seed and NE planted apple seeds.

4-21-1965 J. Kerr set CIM by MHD notes. RPs-center line pavement N 10.6', disc in PP SW 47.4' ,and disc in PP SE 122.0.

11-1969 Sankstone Took measurements.

6-9-1970 County Surveyor removed CIM and checked rod below. Set 1/2" rod in place, all old ties still in place.

7-6-1972 County Surveyor reset corner with CIM over rod found below.

6-3-1992 County Surveyor found CIM in blacktop leaning NE. Checked ties confirming this and left as in for now.

6-4-1992 County Surveyor dug out CIM found and 1/2" rod below. RPs- 47.32' SW to old disc in PP, found 5/8" rebar set in 1970, distance good, but not inline.

6-24-1993 County Surveyor set pk nail in location shot in 1992 from ref rod in yard SW of corner. Corner is 11' south of centerline CR 34 and in line of centerline CR 3 north & south.

7-12-1993 County Surveyor set square pipe w/cap at PK nail location set. CSD in PP #40 ESE 121.16.

6-3-1999 County Surveyor found 1" square pipe w/cap in good condition.

8-12-2002 County Surveyor found 1" square pipe w/cap in good condition.

9-23-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-29-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.

8-26-2008 County Surveyor found 1" square pipe w/cap at surface in good condition. Set ref pipe and referenced corner for 2008 construction.

9-19-2008 County Surveyor removed 1" square pipe w/cap.

2-11-2009 County Surveyor set 1" square pipe w/cap at surface from 2008 overlay tie out.

8-24-2011 County survey crew found 1" square pipe with cap in good condition.