Certificate of Location of Government Corner

ID#: 753405 **Description:** S SEC COR 33 34 75 **Date Set:** 2/11/2009 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is at the surface.
The corner falls 13' south of centerline of CSAH 34 and 9' east of wood fence south
Bottle cap in PP S 34.59'
Mn/DOT R/W monument N 63.05'
Ref. Iron SSW 38.81'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 80.0 set post and drove 10" charred stake to sections 3-4-33-34 and built mound, trench, and planted osage orange seeds NE and apple seeds.

7-1873 Hunter Pg.233 No.235; Found stone with stake on east side, center road.

10-1919 McGhie & Betts stone found meas. west 2634.6 N 2635.5

10-1921 Chas Larson (P.362B) 4 Watts Bros found limestone 4 x 8 x 24 P.233 1/16 south set concrete slab 7 x 12 x 20 19.43 then 20.00 to 1/4 3-4 a hard head boulder.

4-22-1965 County Surveyor set CIM over 5/8"x12"rod. RPs- Disc in PP S 29.5, 3" monument N 63.05'. This corner really set by doubling from SW 33 over S 1/4 33.

6-9-1970 County Surveyor removerd CIM and checked rod below. Set 1/2" rod in place 2.95 south from south edge concrete pavement, and 4.0' east of line of fence north. NE edge of t steel post for "For Sale" sign easterly post SE 57.81. Found 1/2" rod set M & L east as 1/16 corner. Lowered rod to some 6"+ deep to sve corner. Corner lies 3' south of south edge pavement. RPs-Punched caross cut in west end drive culv,2nd ridge SW 43.39, punched cross cut in east end drive culv. 4' west of South 23.64, and NE corner of attached garage SSW 112.5.

7-6-1972 County Surveyor found rod set 6-70 after removing CIM for grading. Reset corner with CIM.

8-5-1977 County Surveyor dug on west side of CIM to check conditions for digging further west with backhoe for stone recorded in old field book dated 1919 in McGhie office. Found area cut to clay 14" down.

6-3-1992 County Surveyor found CIM in good condition. Rps-12.9' north to centerline of CR 34, 34.62' south to bottle cap in & power pole, set 1/2" reference rod 5' east of wood fence.

6-24-1993 County Surveyor set 1" square pipe w/cap at surface of CR 34 over CIM tie out in 1992. RPs-centerline CR 34 north 12.9'. the corner falls plus or minus 9' east of wood fence running south. Checked 1992 tie to bottle cap in power pole south 34.62'.

6-24-1993 County Surveyor set 1" square pipe w/cap from RP's in 1992.

8-26-2008 County Surveyor found 1" square pipe w/cap at surface in good condition. Referenced corner for 2008 construction.

9-19-2008 County Surveyor removed 1" square pipe w/cap.

2-11-2009 County Surveyor set 1" square pipe w/cap at surface from overlay tie out.