Certificate of Location of Government Corner

ID#: 753406 **Description:** 1/4 SEC COR 33 34 75 **Date Set:** 8/5/77 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 25 1/2' south of centerline of WBL of TH 14 and in line with fences north and south.
Punch mark on W side of ring on catch basin ESE 142.00'
1/2" rod between RR tracks on section line N 377'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Michael Karrick, Deputy Surveyor; North between sections 33 & 34.
40.00 chs set quarter section post in mound with trench and pits, charred stake, and planted osage orange seeds NE and SW.

1869 Thomas Hunter's railroad notes show the corner 377' south of the center of the railroad tracks.

5-3-1882 T. Hunter (Field Book 5, Pg. 137) Found quarter post missing and no evidence could be found. Set stake 5.71 chains south of the center of railroad track.

8-5-1977 County Surveyor: the corner now comes in the median of T.H. 14. Set a CIC on a square pipe as the corner at Hunter's recorded measure of 377' south of the center of the RR tracks and in line with the fence south and the fence north (on the North side of the tracks).

5-31-2002 County Surveyor found cast iron cap on telspar pipe at surface in good condition.