Certificate of Location of Government Corner

ID#: 753506 **Description:** 1/4 SEC COR 34 35 75 **Date Set:** 10/24/2006 **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 68' south of centerline of east bound lane of TH 14
Concrete flume SE corner (intersect corner on west side of flume) NE 25.8'
County Survey Disk in N side 10" Box Elder W 9.78'
Post w/sign SSE 6.2'
This corner is located by GPS reference stations "Look Out A & B"

Corner History:

1854 Gov't Notes: John Ball, Deputy Surveyor; 40.00 chs set 1/4 sec. post and drove charred stake, built mound with trench, and planted osage orange SW and apple seed NE.

1869 Thomas Hunter's railroad notes show the corner 564' South of the centerline of the railroad tracks.

4-29-1871 Robert Perry (Pg.159, No.182) County Surveyor measured 560.84' from the corner North to the centerline of the railroad tracks.

11-1969 Leonard Sankstone set the corner 564' South of the centerline of the railroad tracks and on the line between the section corners.

8-11-1977 County Surveyor, the corner comes in a deep ditch on the South side of the East bound lane of T.H. 14. Set a 1 1/2" square by 24" long pipe as the corner 564' South of the centerline of the railroad tracks and on the line between the section corners. Set 5/8" rod on the section line in the center of the track.

1-13-1978 County Surveyor put a CIC on the pipe set 8-11-1977.

8-13-2002 County Surveyor found cast iron cap on telspar pipe lying flat in ditch bottom.

10-24-2006 County Surveyor set 5' telspar w/CIC up 0.4' from computed coordinates. Monument falls in ditch bottom with water running in ditch. CSD w/concrete nail in north side of 10" Box Elder W 9.78', set post w/sign SSE 6.2' on backslope.