Certificate of Location of Government Corner

ID#: 753605 **Description:** S SEC COR 35 36 75 **Date Set:** 2/12/2009 **County:** Olmsted

Section: 36 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is at the surface
The corner falls in centerline of CSAH 34, in centerline of twp road south and 5' east of centerline of twp road north
County Survey Disk in NW side PP #50021 NE 56.83'
Mn/DOT R/W monument NE 58.24'
Ref iron SSE 114.18'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes Karrick 80.00 set post and drove charred stake to sections 1-2-35-36 built mound with trench. Planted SE Osage Orange seeds NE Apple seeds.

5-1877 T. Hunter (P.360 No.351 S.2) D.Fallon found stone in center road in line fence south, claimed set at site of original corner. 1/16 west set stone 4 x 7 x 20 M&L 19.89. South set marked stake 29.47 then 10.00 to 1/4 1-2 a fence post in mound. Also set marked stake west of above stake 19.99 which was set on N-S 1/16 line 10 chs from E-W 1/4 line 2.

6-9-1970 County Surveyor found long cross in centerline pavement, also other markers suspicous as to being also crosses. Cross accepted as corner ties 33' east of RW marker on Sw corner inters and 33' west like marker at SE corner inters (SW marker badly tilted). Hole in top 3" mon 286 + 84.5 SE 59.94. Hole in top 3" mon 286 + 84.5 NE 58.65. These mon are not opposite at 90° from centerline only south mon used as 33' to set cross in pavement. The northeast mon would be about 30' east on 90° from centerline. Pepsi cap on NW side new power pole (no number) SW 60.5. Cross used most easterly and longest and deepest one.

6-3-1992 County Surveyor found chisel cross in conc checked ties 59.77' SE to Mn/Dot mon 58.58' NE to Mn/Dot mon. Set 1/2" Ref rod. RP's 22.52' NE to PP #50022 11.0' west to centerline of N-S road. Angle at Ref rod, angle RT S 35, 36 to top of radio tower 307° 39' 03.5" to S 35, 36 VA 900004 Dviz. SD 114.135 HD 114.135. Jackhammered conc out so mon can be set after blacktopped

6-28-1993 County Surveyor turned out June 1992 ref angle of 307° 39' 03.5" for 114.135 (set P.K. nail).

7-12-1993 County Surveyor set 1" square pipe w/cap in centerline C.R. #34 at surface of new blacktop at P.K. location set out 6-28-93 checked Mn/Dot mon ties ok. The corner lies with centerline south and ± 5' east of centerline north.

8-12-2002 County Surveyor found 1" square pipe w/cap in good condition.

1-28-2008 County Surveyor found 1" square pipe w/cap at surface in good condition.

9-5-2008 County Surveyor found 1" square pipe w/cap at surface in good condition. Referenced corner for 2008 construction.

9-19-2008 County Surveyor removed 1" square pipe w/cap.

2-12-2009 County Surveyor set 1" square pipe w/cap at surface from 2008 overlay tie out.

8-24-2011 County survey crew found 1" square pipe with cap in good condition