Certificate of Location of Government Corner

ID#: 813104 **Description:** S 1/4 SEC COR 31 81 **Date Set:** 12/21/2005 **County:** Wabasha

Section: 31 **Township:** 108N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' north of centerline of E-W twp road, in line with fence south and 6 1/2' east of fence north
County Survey Disk in leaning CP NNW 39.82'
County Survey Disk in PP #32981 NE 125.51'
County Survey Disk in PP #43493 SE 39.22'
This corner is located by GPS measurement

Corner History:

9-25-1853 Gov't Notes John Ball, Deputy Surveyor West between sections 6 and 31. 40.00 chs. Set post for quarter section corner. Burr Oak 12 in. S12 1/2ºW 254 lks. And dug trench per instructions. 79.20 chs. To township corner. Found no other records of this corner.

11-16-1979 Olmsted County Surveyor dug in line with the fence South and in the center of the road. Found a three-sided greenish boulder (5"/7"/8" by 16" long and coming to a point) standing 1 1/2' deep with its base in clay. Drove a 5/8" x 23" rod where the stone stood and set the stone on the West side of the rod.

11-19-1979 Olmsted County Surveyor dug again to cover a corner location at prorated Gov't measure from the N.W. Cor. Sec. 6 to the fence line north at the N.E. Cor. Sec. 6. This location came approximately 12' East of the stone found. Found nothing further. Traversed to the fence corner at the S. 1/4 Cor. Sec. 6 and the fence corner at the Center Section 6 and found the fence line on the N-S quarter line of Sec. 6 to agree with the stone found at the N 1/4 Cor. Sec. 6.

8-14-1980 Olmsted County Surveyor accepted the location of the stone found 11-16-1979 as the corner location and set a Cast Iron Monument over the iron set 11-16-1979. This corner fits the lines of occupation the fence line South and the center of the E-W road, and our traverse in Section 6 shows that it is probably the corner used to subdivide Section 6.

12-15-2005 Olmsted County Surveyor found CIM down 0.5' leaning to the south.

12-21-2005 Olmsted County Surveyor found CIM w/top section broken off down 1.1' in good condition. Removed broken CIM and found 5/8" rerod w/stone on west side down 2.1' in good condition. Removed rerod and stone and set 7' telspar pipe w/cast iron cap down 0.4'.