Certificate of Location of Government Corner

ID#: 813105 **Description:** SW SEC COR 31 81 **Date Set:** 10/13/2011 **County:** Wabasha

Section: 31 **Township:** 108N **Range:** 11W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is down 0.5'
The corner falls 2' south of centerline of E-W twp road and 3 1/2' east of centerline of N-S twp road
PK nail in NE side PP #32883 NW 48.74'
Nail and plastic disc in NW side PP #32882 SW 48.84'
This corner is located by GPS reference stations "Corbin & Corbin A"

Corner History:

1853 Gov't Notes, John Ball, Deputy Surveyor North between Sections 6 and 1 80.00 chs. Set section corner post. Drove charred stake and made mound and trench.

1875 State law required that the northeast corner of each township must have a permanent marker which should be either a stone not less that eight inches square and two feet long, or an iron post not less than two inches square and 30 inches long and having a head six inches square. T. Hunter set 8x8 topped cut limestone.

8-16-1972 Olmsted County Surveyor dug with cat and found 8"x8" topped limestone monument. Drove 1 1/4" pipe 2' long on east side. Corner came 5.2' east and .3' north of bolt found and removed. Set drag tooth over stone.

7-6-1973 Olmsted County Surveyor placed: 6" C.I.M. over stone.

12-15-2005 Olmsted County Surveyor found CIM down 0.5' leaning to the south.

12-20-2005 Olmsted County Surveyor removed leaning CIM and found 12"x12" oblong topped limestone down 1' in good condition. Set drill hole in top center of stone. Set 1/2" rerods on N-S-W sides of stone.

10-13-2011 County survey crew found 12"x12"x24" oblong limestone with drill hole in good condition. Found 1/2" rods on north, south and west sides of stone. Removed the stone and rods and replaced with a 5' telspar pipe with cast iron cap.