Certificate of Location of Government Corner

ID#: 813204 **Description:** S 1/4 SEC COR 32 81 **Date Set:** 9/9/2012 **County:** Wabasha

Section: 32 **Township:** 108N **Range:** 11W **Monument Description:** Brass Plug with Punchmark

Reference Ties:

The monument is at the surface.
The corner falls 4' south of centerline of twp road east, in centerline of twp road west and in centerline of CSAH 10.
This corner is located by GPS measurement

Corner History:

9-25-1853 Gov't Notes John Ball, Deputy Surveyor West between sections 5 and 32. 40.00 chs. Set post for quarter section corner. Burr Oak 6 in. S3ºE 40 lks. Burr Oak 8 in. N7ºE 232 lks.

10-14-1921 Olmsted County Highway Department (C.H.D. Book 36 Page 1) set a hub at "Intersection of E&W and N&S roads midway between fence lines which are well defined".

11-25-1944 Olmsted County Highway Department (C.H.D. Book 168 Page 31) records a hub as the corner.

1979 DNR found a spike in centerline N-S road, 2' North of the centerline of the road West and 4' South of the centerline of the road East.

1979 Olmsted County Surveyor found spike recorded by the DNR.

1-1980 Kleinschmidt and Webber Inc. found monument (no description). Used corner for a survey in Section 32.

7-10-1980 Olmsted County Surveyor found a 1/2" by 3" pipe at the location of the spike found in 1979. Dug with backhoe. In a road approximately 3 1/2' deep found a 1" x 2" hub 2.45 West and 1.35 North of the 1/2" pipe location and a 1" x 2" hub with a 120d spike beside it 2.3 West of the 1/2" pipe location. Dug further and in an old road 6' deep found a 1" x 2" hub 2.3 West and .1 South of the 1/2" pipe location. This road was on bedrock and we found nothing further.

8-14-1980 Olmsted County Surveyor set a Cast Iron Monument over a 1/2" x 18" rod as the corner at the location of the 1" x 2" hub found 6' deep on 7-10-1980. We believe this hub is the corner set here by the County Highway Department in 1921. The 1921 and 1944 County Highway Department topography shows that this corner fit closely a fence West on the South side of a former school property in the N.E. corner of the N.W. 1/4 Sec. 5 and a fence West near a former property line South of the 1/16th South.

4-1989 DNR dipped corner checked ties.

12-16-2005 Olmsted County Surveyor found CIM in good condition down 0.3'. PP to the SW gone, PP to the SE ok, did not look for culvert. Measured location using GPS.

9-9-2012 CIM has been destroyed due to reconstruction of CSAH 10. Olmsted County survey crew set a brass plug with punch mark at previously measured position.