Certificate of Location of Government Corner

ID#: 813504 **Description:** S 1/4 SEC COR 35 81 **Date Set:** 10/5/1977 **County:** Wabasha

Section: 35 **Township:** 108N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' south of centerline of E-W twp road and 2 1/2' east of fences north and south
County Survey Disk in E side CP NNW 33.41'
County Survey Disk in W side of corner post South, 28.55'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes: Set post for quarter corner. BT's White Oak 10" N 69°E 69 links. White Oak 14" S 59°W 65 links. 14" Burr Oak (line tree) 1.53 chains N???

10&11-1900 W.Fraser (P.692-8 No.615) (see field Bk 9 P.61-67) found stone in place as 1/4 cor accepted many years as corner. Lies 15 lks east and 6 lks south to be M&L. Meas west 40.08 (2645.28) east 39.78-1/4 (2625.48) 1/16 west "2" found stone in place as 1/16 cor lies 11(7.26) lks too far east and 1-1/2 (1.0) links too far south to be M&L left as found but did not used it as corner used M&L 20.02. Also corners "3" and "4" found stones simularly too far east sec NW 2 used correct for work but left stones. 1/16 south "18" drove stake line and gov't prop south 19.36-1/4 then 19.71-1/4 south line section straight. E-W 1/4 line is straight by meas the north 1/2 of east sec line 2 must be real short.

6-14-1977 Olmsted County Surveyor dug out entire surface of E-W road from 5' E to 5' W of the N-S fence 4-1/2 deep to clay. Fill to clay. Found nothing.

6-15-1977 Olmsted County Surveyor dug and found 5" x 18" x 16" limestone 1/2' deep with 5/8" bolt on the east side and a sickle section on the SW side and a stake on the S side. Stone .73 E and .2 N of T.N. set in the center of the road and in line with the fence S. Believe this stone the one recorded by W.F. as 1-1/2 lks S and 11 lks east of his M&L 1/16th. 1/64th west of above 1/16th: Dug for stone recorded by W.F. (Bk 9 P.64) as 11 lks too far east and 1-1/2 lks too far S found nothing. 20 rds E of N 2-3 dug for stone recorded by W.F. (Bk9 P.64) as being 16 lks too far east and 4-1/2 lks too far S. Point came in line with E edge of field road S which appears to be where old fences stood. Area cut, found nothing.

10-5-1977 Olmsted County Surveyor set a cast iron cap on telspar pipe at the intersection of the line from the S 1/4 2 (found) over the center 2 (found) and the line from the NW cor 2 over a pt 1-1/2' lks N of the stone found at the 1/16 west as per W.F. (old field book no 9). Corner 2' S centerline E-W road and 2-1/2' east of the fence north and S. RP's: Spike and CSD SW side 10" Elm NW 86.08. Spike and CSD E side corner post NNW 32.70 (this monument 5.0 east of 6-30-77 location with calc. error)

12-17-2009 County survey crew found damaged telspar pipe with no cast iron cap. The damaged segment of the pipe was near the surface and lower section was in good condition. Cut off the damaged top section and set new cast iron cap on the telspar pipe down 0.7'