Certificate of Location of Government Corner

ID#: 823304 **Description:** S 1/4 SEC COR 33 82 **Date Set:** 7/3/2008 **County:** Wabasha

Section: 33 **Township:** 108N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls on south side of drainage ditch
Post w/sign 2' east
This corner is located by GPS reference stations "Elgin A & B"

Corner History:

1853 Gov't Notes: John Ball, Deputy Surveyor west on north boundry of section 4. 35.75 chs. Brook 4 lks. wide running NE. 40.00 chs. Set quarter section post. Made mound with trench.

10-1894 William Fraser (P. 553 No. 510), County Surveyor, found stone set by Wabasha County Surveyor.

5-1931 Olmsted County Highway Department (B. 63 P. 13) found flat limestone 5" above surface.

6-25-1973 Olmsted County Surveyor found 4"x12"x15" recorded limestone 2' deep. Set 1 1/4"x30" pipe on north side of stone with CIM on top.

12-11-2006 Olmsted County Surveyor visited area of corner. Found nothing. Drainage ditch goes through area of corner.

7-3-2008 Olmsted County Surveyor set out area from GPS reference and found nothing. Area is now a drainage ditch. Set a 6' telspar pipe w/CIC up 0.3' from GPS reference. Corner falls in South side of drainage ditch.